

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	12/21/2023	Time:	12:03 PM
Name of School Corporation:	HAMILTON SOUTHEASTERN SCHOOLS			Corp ID:	293005
Address of School Corporation:	13485 Cumberland Rd				
City:	Fishers	Zip:	46038	County Number:	29
VIN:	1T7Y54D28J1123485	License Number:	17735	Bus Number:	280
Make of Body:	Thomas Built Buses, Inc.	Year:	2016	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D			Mileage:	69855
Inspection Status:	O	Inspected By:	Joel Flores	PE:	7415

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-4	Any front turn signal does not function properly
34-1-5	See Notes: Any defect inspector deems a violation not listed
68-1-1	Washers do not function properly in any manner
70-1-2	There are intersecting cracks in the windshield area covered by the wipers

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
11-2-2	A bumper does not meet manufactures specifications
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.