

## REPORT OF SCHOOL BUS INSPECTION

|  |                                 |  |
|--|---------------------------------|--|
| <b>Type of Inspection:</b> Annual                      | <b>Date:</b> 6/13/2024          | <b>Time:</b> 9:31 AM                   |
| <b>Name of School Corporation:</b> EASTERN HANCOCK CSC | <b>Corp ID:</b> 303145          |  |
| <b>Address of School Corporation:</b> 10370 E 250 N    |                                 |  |
| <b>City:</b> Charlottesville                           | <b>Zip:</b> 46117               | <b>County Number:</b> 30               |
| <b>VIN:</b> 4DRBUC8NXJB046760                          | <b>License Number:</b> 16705    | <b>Bus Number:</b> 8                   |
| <b>Make of Body:</b> IC Corporation                    | <b>Year:</b> 2018               | <b>Make of Chassis:</b> IC Corporation |
| <b>Year:</b> 2018                                      | <b>Mileage:</b> 69477           | <b>PE:</b> 8184                        |
| <b>Bus Type:</b> C                                     | <b>Inspected By:</b> Jeff Stone |  |
| <b>Inspection Status:</b> O                            |                                 |  |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 16-1-1                 | There are any leaks from the differential, pinion seal, hubs or wheel seals |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 16-2-1                 | When any wheel seal is leaking and includes evidence of wet contaminated brake friction material and accompanied by evidence that further leaking will occur. |

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.