

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 7/30/2024	<b>Time:</b> 9:25 AM
<b>Name of School Corporation:</b> NORTHERN WELLS COMM. SCHOOLS	<b>Corp ID:</b> 908435	
<b>Address of School Corporation:</b>		
<b>City:</b>	<b>Zip:</b>	<b>County Number:</b> 90
<b>VIN:</b> 4DRBUC8N1GB107549	<b>License Number:</b> 10071	<b>Bus Number:</b> 35
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2015	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2015	<b>Mileage:</b> 172660	<b>PE:</b> 6921
<b>Bus Type:</b> C	<b>Inspected By:</b> Steve Spallinger	
<b>Inspection Status:</b> O		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-3	The seat belt cutter is contained in a compartment.
50-1-2	The seat belt cutter is not secured using a positive fastening method.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-2	Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**