

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	10/10/2024	<b>Time:</b>	9:33 AM
<b>Name of School Corporation:</b>	TELL CITY-TROY TWP SCHOOL CORP	<b>Corp ID:</b>	626350		
<b>Address of School Corporation:</b>	832 17th Street				
<b>City:</b>	Tell City	<b>Zip:</b>	47586	<b>County Number:</b>	62
<b>VIN:</b>	4UZABRDTX9CAE2429	<b>License Number:</b>	31519	<b>Bus Number:</b>	14
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2008	<b>Make of Chassis:</b>	Freightliner
<b>Year:</b>	2009	<b>Mileage:</b>	Unknown		
<b>Bus Type:</b>	C	<b>Inspected By:</b>	Philip Lubbers	<b>PE:</b>	7703
<b>Inspection Status:</b>	O				

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-10	See Notes: Any defect inspector deems a violation not listed
30-1-3	See Notes: Any defect inspector deems a violation not listed
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
23-1-6	Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
11-2-2	A bumper does not meet manufactures specifications
24-2-2	Any body surface protrudes beyond the normal limits of the body structure

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**