

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|--------------------------------|---------------------------|-----------------|----------------|------------------|--------------------------|
| Type of Inspection: | Annual | Date: | 8/21/2025 | Time: | 10:45 AM |
| Name of School Corporation: | ELKHART COMMUNITY SCHOOLS | | | Corp ID: | 202305 |
| Address of School Corporation: | 2720 California Rd | | | | |
| City: | Elkhart | Zip: | 46514 | County Number: | 20 |
| VIN: | 1T7YT4E22B1138201 | License Number: | 74989 | Bus Number: | 37 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2010 | Make of Chassis: | Thomas Built Buses, Inc. |
| Bus Type: | D | | | Mileage: | 157723 |
| Inspection Status: | O | Inspected By: | Joseph Hartman | PE: | 7257 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 34-1-2 | The headlight dimmer switch fails to operate properly |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 70-2-4 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |
| 59-2-6 | LED type lights have 50% or more pixels inoperable in one light. (NOTE: one letter in the word "STOP" equals one light.) |

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.