

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|-------------------------------|------------------------|------------------|-------------------------|--------------|
| Type of Inspection: | Semi-Annual | Date: | 10/24/2025 | Time: | 11:02 AM |
| Name of School Corporation: | RANDOLPH CENTRAL SCHOOL CORP. | | | Corp ID: | 686825 |
| Address of School Corporation: | 103 N East St | | | | |
| City: | Winchester | Zip: | 47394 | County Number: | 68 |
| VIN: | 1T88T9E24E1164487 | License Number: | 5648 | Bus Number: | 6 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2012 | Make of Chassis: | Freightliner |
| Year: | 2014 | Mileage: | 164725 | PE: | 6921 |
| Bus Type: | D | Inspected By: | Steve Spallinger | | |
| Inspection Status: | O | | | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 24-1-2 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |
| 54-1-1 | Stanchions, guardrails, guard panels or barriers are insecurely attached |
| 82-1-2 | See Notes: Any defect inspector deems a violation not listed |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 59-2-3 | Stop arm does not fully extend to a right angle to the bus |
| 7-2-4 | Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection). |

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.