

# REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 6/17/2026	<b>Time:</b> 9:47 AM
<b>Name of School Corporation:</b> SOUTH PUTNAM COMMUNITY SCHOOLS	<b>Corp ID:</b> 676705	
<b>Address of School Corporation:</b> 3999 S US 231		
<b>City:</b> Greencastle	<b>Zip:</b> 46135	<b>County Number:</b> 67
<b>VIN:</b> 1GB3G3BG9B1103956	<b>License Number:</b> 5552	<b>Bus Number:</b> 1131
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2011	<b>Make of Chassis:</b> GMC
<b>Year:</b> 2011	<b>Mileage:</b> 96195	<b>Year:</b> 2011
<b>Bus Type:</b>		
<b>Inspection Status:</b> <input type="radio"/>	<b>Inspected By:</b> Tyler VanNess	<b>PE:</b> 7583

## Violations - Rejected

### Inspection Code Description

## Violations - Out of Service

### Inspection Code

### Description

70-2-4 Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

### Bus Type Description