

# REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Semi-Annual	<b>Date:</b> 12/29/2011	<b>Time:</b> 12:39 PM
<b>Name of School Corporation:</b> HANOVER COMM. SCHOOL CORP.		<b>Corp ID:</b> 454580
<b>Address of School Corporation:</b> 14525 Wicker		
<b>City:</b> Cedar Lake	<b>Zip:</b> 46303	<b>County Number:</b> 45
<b>VIN:</b> 1GDHG31FXX1050424	<b>License Number:</b> 19951	<b>Bus Number:</b> 24
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 1999	<b>Make of Chassis:</b> Blue Bird Corporation
		<b>Year:</b> 1999
<b>Bus Type:</b>	<b>Mileage:</b> Unknown	
<b>Inspection Status:</b> <input type="radio"/>	<b>Inspected By:</b> Nathan Sherer	<b>PE:</b> 7029

## Violations - Rejected

### Inspection Code Description

## Violations - Out of Service

### Inspection Code

### Description

36-2-1 Exhaust leak occurs in the exhaust system prior to the muffler outlet.

### Bus Type Description