



Proposed Code Change  
State Form 41186R

RETURN TO:  
INDIANA DEPARTMENT OF HOMELAND SECURITY  
CODE SERVICES SECTION  
302 W. Washington Street Room W246  
Indianapolis, IN 46204

<b>FOR OFFICE USE ONLY</b>
Received 6/29/09
Code 50.6-09

INSTRUCTIONS: *Only TYPED copy accepted.*  
*(KEY – Dashed line through material to be deleted, underline material to be added)*  
*Use second sheet for any material requiring more space.*

Code Title 2009 Indiana Residential Code		Edition First Edition	
Section number and title R502.8.1.1 Alternate drilled joist holes, Figure R502.8		Page 1 of 1	
Proponent Craig Wagner		Title Chief Building Inspector/ IABO Code Comm. Member	
Address 220 W Van Buren St, Columbia City IN 46725		Phone 260-248-3111	
PROPOSED CODE CHANGE (Check One)			
<input type="checkbox"/> Change to read as follows <input checked="" type="checkbox"/> Add to read as follows <input type="checkbox"/> Delete and substitute as follows <input type="checkbox"/> Delete without substitution			
<p>Bring forward from the 2005 Indiana Residential Code the amendment for section R502.8.1 and rename as follows: <b><u>R502.8.1.1 Alternate drilled joist holes.</u></b></p> <p>Bring <b><u>Figure R502.8</u></b> forward from the 2005 Indiana Residential Code.</p>			
REASON AND FISCAL IMPACT			
<p>This section and figure from the 2005 InRC has been working well and gives installers another option.</p> <p><b>Fiscal impact:</b> this proposal reduces the cost of construction in a 1,500<sup>SF</sup> approximately \$280 where joist size does not need to be increased to accommodate a 3" drain branch.</p>			
REVIEW RECOMMENDATION			
Approve			
Disapprove			
Approve as amended			
Further Study			