	Significant differences between current code and most recent edition	Specific issues the updated code is designed to address	Change would require additional regulation or reduced regulation?	Expected fiscal impact	Health or safety concerns addressed by code
	Updated definitions refining the				
	distinction between a stage and a raised	Clarifies that a raised platfrorm may			
202	platform in assembly occupancies	have horizontal sliding curtains	reduces	(\$50,000)	Clarifies current code
	Updated definitions of fire and	recognizes new lumber treatment			Updates code to recognize new
202	preservative treated wood,	technology	n/a	(\$50,000)	technology
202	Definition of penthouse revised to	Clarifies that uppermost portion of a stairway to a roof is not a story	raduada	(\$10,000)	Clarifies current code
202	include stairways	Small food processing	reduces	(\$10,000)	
		establishments, such as a bakery or			
	Clarification of the occupancy for small	catering kitchen less than 2,500 s.f.			
	food processing establishments	become a B-occupancy, easing the			
		requirements for such small-scale		(\$20,000)	
304.1		operations. These have frequently been	reduces	(\$20,000)	Improves current code
		interpreted to be assembly or			
		educational occupancies under the			
	Addition of training and skill	current Indiana code, and have been			
		the subject of a number of past			
	tutoring centers, and gymnastics studios				
304.1	to Business Group B.	classification.	reduces	(\$100,000)	Improves current code
	Distilleries, breweries, wineries, storage				
		Clarifies code reqiurements for			
		occupancies and uses currently not defined in Indiana code	raduada	(\$100,000)	Improves current code, recognizes marketplace changes
307, 311			reduces	(\$100,000)	
		Aligns with common state licensing			
	Revision of requirements for certain	requirements. The changes include			
	custodial care facilities	deleting outdated terms used in the			
		code, and incorporation of new sub-			Updates code to recognize
308.3		categories to more closely align with common practices in the marketplace.	reduces	(\$50,000)	changes in marketplace and licensing regulations
500.5				(\$00,000)	
		Allows owner-occupied lodging			
	Defines lodging houses, expands uses	houses with five or fewer guest rooms			
	permitted in R4 occupancy	to be regulatedunder residential code.			
		Expands R-4 occupancies to include	na dua na	(\$400,000)	Improves current code, recognizes
310		custodial care	reduces	(\$100,000)	marketplace changes Improves current code, recognizes
	Water supply to fire pumps in tall mass	Addresses issue of contribution to fire			marketplace changes, closes
403.3	timber buildings		adds	\$50,000	loophole
		Clarifies requirements for issues such			·
		as egress travel through atriums,			
	Numerous improvements in code	smoke control and horizontal	l		l
404	requirements related to atriums	assemblies	adds	\$0	Improves current code

			[	1	
	Now sociops addressing private garages				
	New sections addressing private garages,	allows multiple small private garages			
		to be grouped and classified as U			
		occupancies if separated by fire			Updates code to recognize
406	family housing developments	barriers	reduces	(\$10,000)	marketplace changes
		Relaxed requirements for shared			
		living spaces, group meeting rooms,			
		therapeutic spaces and shared			
		domestic cooking facilities in			
	shared living space regulations relaxed	occupancies such as nursing homes.			
	Shared iving space regulations relaxed	The requirements in the current			
		Indiana code for such spaces have			Updates code to recognize
		been the subject of numerous			changes in marketplace and
407	7	variances.	reduces	(\$400,000)	licensing regulations
		Allows 1-hour rated horizontal sliding			
		doors to be used a stage proscenium			
		openings, instead of fire rated			Updates code to recognize new
410.3.5	5	curtains	adds	(\$10,000)	technology
		Commonly called "escape rooms",			
		spaces such as these have been the			
		subject of numerous variances			Improves current code, recognizes
		because the current code is silent			marketplace changes, closes
411.5	occupancy type.	regarding these types of occupancies.	adds	(\$10,000)	loopholes
	Clarification of occupancy type and				
	requirements for energy storage systems				
	Additional clarification to allow fire walls				
	to be used to create multiple control	Allows larger Group H occupancy			Updates code to recognize new
414.2.2	Irooms in high hazard occupancies	buildings	reduces	\$0	technology
414.2.3		ballaligs		\$0	
	Domestic cooking in ambulatory care	Relaxes requirements for domestic			Updates code to recognize new
422.7		•	adds	(\$5,000)	technology and marketplace changes
422.1				(\$5,000)	
					Addresses shifting of tornado alley eastward to more populated
	Storm chalter requirements	Poquiros storm sheltors in critical			
	Storm shelter requirements	Requires storm shelters in critical emergency operation facilities, and E			areas, improves building resiliences, protects schools from
402			adds	\$100,000	tornadoes
423		occupancies		\$100,000	
		Evenneign of play structure			
		Expansion of play structure classifications to include uses for			
	Change in definition of and				
	requirements for play structure	adults, such as rock-climbing walls,			
	occupancies	laser tag arenas, trampoline and			
		skydiving facilities. Facilities such as			Updates code to recognize new
		these have been the subject of a	reduces	(\$20,000)	technology and marketplace
424	+	number of past variances.	reduces	(\$20,000)	changes

		Clarification of requirements for			
		occupied roofs, including clarifying			
		that they are not to be considered in			
		the allowable story restrictions.			
		Numerous buildings now have			
	Clarification of requirements for	occupied roofs, and they are often			
	occupied roofs				
		used as an amenity in some			
		developments. Repeated variances			
		have had to address these as the			Updates code to recognize new
		current code is lacking in information			technology and marketplace
503		regarding current marketplace trends.	reduces	(\$50,000)	changes
	Revisions to the allowable height and	Makes code more user friendly.		· · ·	
503, 504, 506	area requirements		n/a	\$0	Improves code
	Addition of fire classification				
508, 509	requirements for mass timber structures		reduces		
		Makes it easier to incorporate			
	Clarifications to the open mezzanine	enclosed mezzanines in multiple			Updates code to recognize new
505	requirements	occupancy types	reduces	(\$50,000)	technology
		Basements now allowed in unlimited			Updates code to recognize new
507	Basements in unlimited area buildings	area buildings	reduces	(\$100,000)	technology
		The current Indiana code was the first			
		version of the model code to define			
		and address live/work units such as			
		an art studio, chiropractor's office, or small funeral home which also include			
		a private residence. More recent			
		model codes have greatly enhanced			
		and improved the code provisions for			
		these types of facilities. Another			
		example frequently seen in past			
		variance applications to the			
		Commission has been small, one-			
		room school buildings with an			Updates code to recognize new
	Reformatting and clarification of	apartment used by certain religious			technology and marketplace
508.5	requirements for Live/Work Units.	communities common in Indiana.	reduces	(\$10,000)	changes
		Allows combustible stairways to be			
		used for the full height of the			
		building. These types of buildings are			
		commonly found in the largest cities			
		in Indiana and are frequently the			Updates code to recognize new
	Stairway construction in podium	subject of multiple variances for each			technology and marketplace
510.2	buildings	development	reduces	(\$50,000)	changes
510.2	buildings	development	reduces	(\$50.000)	

		This was the subject of an Indiana			
		amendment in the current code.			
		New codes provide much more			
		comprehensive allowances to allow			
		different types of construction and			
		occupancies to be considered as			Updates code to recognize new
		separate buildings within the same			technology and marketplace
	in buildings.		reduces	(\$50,000)	changes
		Extensive coverage of new wood			5
		technology such as engineered			
		lumber, cross laminated timber, and			
		mass timber construction, and			Improves current code, recognizes
	Engineered lumber, cross laminated	creation of new construction types			marketplace changes, closes
	-		adds	\$50,000	loopholes
		<u>_</u>			
		Allowance of freezers and coolers in			
		Type I & II buildings to be constructed			
		of combustible materials; Use of			
	Combustible materials in Type I & II	wood blocking in non-combustible			Improves current code, recognizes
603.1	construction	roof decks and parapets allowed	reduces	(\$50,000)	marketplace changes
		Recognizes new test data for			
		contribution time of mass timber			
		alone and protected by non-			
		combustible construction such as			Updates code to recognize new
703.6, 703.7	Mass timber construction protection	drywall membranes	reduces	\$0	technology
		Eespecially in light frame construction			
	-	such as Type VA apartments this issue			
	,	is often a source of confusion and			
	assemblies permitted to be protectd	contradictory interpretations under			Updates code to recognize new
704	with ceiling membrane		reduces	(\$100,000)	technology
		Allows an enclosed top at exit			
		passageways instead of extending			
202 5		enclosing walls full height to deck	raduasa		Updates code to recognize new
/07.5	Exit passageway enclosures	above Revises definition of structural	reduces	(\$50,000)	technology
		stability, incorporates NFPA 221,			
		allows double fire walls. Double walls			
					Lindetee eede te recennize new
706.2	Eirowall structural requirements	are frequently the subject of variance	adds	(\$50,000)	Updates code to recognize new technology
708.2	Firewall structural requirements	requests		(400,000)	
		Clarification to allow the use of non-			
		fire rated type IIB and VB supporting			Updates code to recognize new
	partitions		reduces	(\$150,000)	technology
/00				(#100,000)	

903.	2	<b>.</b>	adds	\$50,000	loopholes
		fire areas used for bulk storage of			marketplace changes, closes
	Distilled spirit sprinkler requirements	spirit manufacturing and Group S-1			Improves current code, recognizes
		Clarifies sprinkler requirements for Group F-1 fire areas used for distilled			
		Clarifica aprinklar regiuirements for			
903.	2 roofs	below.	adds	\$50,000	loophole
	Sprinkler requirements for occupied	sprinkler system in the building			marketplace changes, closes
		for assembly purposes triggers a			Improves current code, recognizes
		Clarifies when an occupied roof used			
903.	2 Upholstered furniture and mattresses	upholstered furniture and mattresses.	adds	\$0	technology
		used for the manufacture of			Updates code to recognize new
		sprinkler triggers for F-1 occupancies			
		Clarification and reformatting of			
				(* - ) )	Ŭ Ŭ
806.	9 Wood lockers		reduces	(\$10,000)	changes
		be considered an interior finish where			Updates code to recognize new technology and marketplace
		Clarification that wood lockers may			
122.				ψυ	technology
700	7 Mass timber fire ratings	Provides fire ratings for mass timber asseblies based on new test data	adds	\$0	Updates code to recognize new
717.5.	2 Flex duct penetrating a fire barrier	barrier without a fire damper	reduces	(\$150,000)	technology
		Allows a flex duct to penetrate a fire			Updates code to recognize new
71	7 Duct transitions between shafts		adds	(\$50,000)	Improves code
		Allows ducts to transition horizontally			
/ 1				↓	
71	6 walls		adds	\$0	technology
	Doors in double fire barriers and fire	double 1-hour rated walls such as at			Updates code to recognize new
		3/4 rated doors may be used in			
		doors in fire walls, clarifies that two			
	5 Protection of joints and voids	code more user-friendly Incorporates NFPA 221 for double		φυ	
74	5 Drotoction of joints and voids	Reformating and clarifcation to make	reduces	\$0	Improves code
/14.	4 Membrane Penetrations		reduces	(\$500,000)	Improves code
		source of confusion and inconsistent	raduasa		
		membrane. This issue is a constant			
		may interrupt a rated ceiling			
		clarification that a double top plate			
713.1	2 Top of shaft termination		reduces	(\$50,000)	Improves code
		Requirements clarified. Additional			
711,71	2 openings	,	reduces	\$0	Improves code
	Horizontal assemblies and vertical	Reformating and clarfication to make			
709.	4 Smoke barrier continuity		reduces	(\$50,000)	Improves code
		Allows unprotected openings in			
		areas of refuge and elevator lobbies.			
		occupancies and smoke barriers for			
		smoke compartments in I-			
		Revisions to distinguish between			

1	·	Clarifies that multiple Group A fire			
I	Multiple Group A fire areas	areas sharing a common means of			Improves current code, recognizes
		egress are combined in evaluating			marketplace changes, closes
903.2			adds	\$0	loophole
		Requires sprinklers in certain open			
1	Sprinkler requirements for Parking	parking garages. Based on extensive			Improves current code, recognizes
	Garages	use of plastics in automobile			marketplace changes, closes
903.2	2		adds	\$100,000	loophole
I		Clarifies height limitations for 13R			Improves current code, recognizes
	1 1 0	sprinkler systems used in podium type	٤		marketplace changes, closes
903.3.1.2		Ŭ	adds	\$100,000	loophole
j	Corridor and Balcony sprinkler	Closes loophole for open corridors			Improves current code, recognizes
		and shared balcony sprinkler			marketplace changes, closes
903. <u>3.1.2.</u> 2'	2 protection	•	adds	\$50,000	loophole
	Standning requirements at parking	ſ,	1		Improves current code, recognizes
	Standpipe requirements at parking	Revisions consistent with 903.2			marketplace changes, closes
905.3.1	1 garages	changes regarding parking garages	adds	\$50,000	loophole
		,	1		
	Clarification of fire alarm requirements				
Ţ	in multi-story self-storage buildings		reduces		
+	· +'	Recognition of low frequency fire			
1		alarm systems. These systems have			
1		proven to be six times more effective			
Ţ		at waking certain at risk segments of			
I					
1	·   · · · · · · · · · · · · · · · · · ·	the populations, such as children, the			
		elderly, and people who are alcohol		<b>*</b> =0.000	Updates code to recognize new
907.5.2.1.3 v	3 Low frequency fire alarm systems.		adds	\$50,000	technology
1		Provides multiple fire protection			
1		options for attics used for living			Updates code to recognize new
		purposes and not used for living			technology and marketplace
903.2.8	8 for attics used as living purposes	purposes in group R-3 and R-4	adds	\$0	changes
1		Exempts bathrooms of < 55 s.f. from			Updates code to recognize new
1					technology and marketplace
903.3.1.1.2			reduces	(\$100,000)	changes
,	,	, , , , , , , , , , , , , , , , , , ,	1		
Ţ	Requirements for domestic appliances				Updates code to recognize new
		Provides options for protection of			technology and marketplace
			adds	\$20,000	changes
J	,	Increase fire alarm requirements due			
1	·   · · · · · · · · · · · · · · · · · ·	to recent history of dormitory fires.			
1	,	Clarifies that requirements apply to			
1	,	housing operated by the university,			
1	,	but does not apply to housing over			Improves current code, recognize
1		which the school or university does			marketplace changes, closes
	, 0	\$	adds	\$50,000	loopholes
	JUNIVERSITY BUILDINES		auus	φυυ,υυυ	loohiloies

	1		l		
		Clarification of placement of smoke			
		alarms near small bathrooms and			
		near cooking appliances. This is a			
	Smoke alarms near small bathrooms and				Updates code to recognize new
		-	reduces	(\$50,000)	technology
507.2.11		Adds a requirement for a fire		(\$00,000)	
		command center in F-1 and S-1			Improves current code, recognizes marketplace changes, closes
011	Fire command centers in F-1 and S-1		adds	\$50,000	loopholes
911		bululings larger than 500,000 s.i.		ψ50,000	
		Reformatting to clarify CO detector			
915	Carbon monoxide detectors		adds	\$0	Improves code
513		requirements in various occpancies		ψ0	
	Common path of travel requirements for	Common path of travel requirements			
		for unoccupied mechanical rooms and			Updates code to recognize new
1006.2.1		penthouses eliminated.	reduces	(\$50,000)	technology
		Clarifies that even though an			
		occupied roof is not a story, the			
		occupant load of the roof does not			
	roofs clarified.	need to be combined with the story			Updates code to recognize new
1000.0		below, but can be considerred as if		(**********	technology and marketplace
1006.3		the roof is a story	reduces	(\$50,000)	changes
	Inclusion of new occupant load factors,				
	office occupant load factor for offices				Updates code to recognize new
	changed to 150 s.f./occupant	Reduces occupant load requirements	and the second	(\$500,000)	technology and marketplace
1004.1.2			reduces	(\$500,000)	changes
		Eliminates common path of egress requirement for single exit stories.			Updates code to recognize new
	Single exit stories	Exiting requirements now based on			technology and marketplace
1006.3.4		•	reduces	(\$250,000)	changes
				(+)	Improves current code, recognizes
	Remoteness test requirements	New remoteness test requirements to			marketplace changes, closes
1007.1	·	address converging stairs	adds	\$25,000	loopholes
		Light level increased in exit access			Improves current code, recognizes
	Stairway illumination	stairs except at auditoriums and			marketplace changes, closes
1008.2.1		theatres	adds	\$15,000	loophole
					Improves current code, recognizes
		Clarifies when an accessible elevator	adda	¢50.000	marketplace changes, closes
1009.2.1		is required to an occupied roof	adds	\$50,000	loopholes
	Interior areas of refuge at level of exit	Interior areas of refuge are now			
	discharge	allowed as an accessible means of			Updates code to recognize new
1009.6.2		egress on the level of exit discharge	reduces	(\$50,000)	technology
		Clear floor space for a wheelchair at		(********	
	Area of refuge floor space increase	an area of refuge increased from			
1009.6.3	0 1	<b>U</b>	adds	\$0	deminimus change
		Maximum 48" door width limitation			
	Door widths	eliminated; new exception allows for			Updates code to recognize new
		reduced door sizes serving single			technology and marketplace
1010.1.1		user spaces such as dressing rooms	reduces	(\$50,000)	changes

1010.1.1.1		Additional elements now allowed to encroach into the clear door opening	reduces	(\$50,000)	Updates code to recognize new technology and marketplace changes
1010.1.1.1		Clarification as to when locks and	Teudces	(\$50,000)	Changes
	Clarification as to when locks and latches	latches shall be permitted to prevent			
	shall be permitted to prevent operation	operation of doors from the egress			
	of doors from the egress side	side. As the desire for more secure			Updates code to recognize new
1010.0.4	_	facilities continues, this is a critically	raduada	(\$50,000)	technology and marketplace
1010.2.4		important topic.	reduces	(\$50,000)	changes
		Incorporation of requirements for			
		"social stairs". These are a design			
		element frequently incorporated in			
		higher education facilities, and now is			
	Herefreile et es siel steire	migrating to other uses. The design			
	Handrails at social stairs	incorporates a seating area that steps			
		up adjacent to an egress stair. The			
		current Indiana code does not			
		recognize this condition and variances			Updates code to recognize new
1030.16		are required.	reduces	(\$100,000)	technology and marketplace
1030.10		Elimination of two-way	leuuces	(\$100,000)	changes
	Two-way communication system from	communication system from service			
		and freight elevators, and residential			Updates code to recognize new technology and marketplace
	_	elevators	reduces	(\$25,000)	changes
1009.0				(\$20,000)	langes
		Clarification regarding use of			
		permanent ladders to provide access			
		to certain areas. The current code is			Updates code to recognize new
		unclear regarding many common uses			technology and marketplace
1011		of permanent ladders	reduces	(\$50,000)	changes
		Means of egress is now allowed to be		(+)	Updates code to recognize new
	Clarification regarding means of egress	through an elevator lobby in certain			technology and marketplace
		conditions	reduces	(\$50,000)	changes
				(******** <b>/</b>	, č
		Increased exit travel distances in			
		Group F-1 and S-1 facilities clarified.			
		This has been a source of confusion			
		for decades. Indiana amendments			
		have attempted to resolve the issue.			
		The newest model codes provide			
		greater flexibility than current Indiana			
		codes. Increased travel distance is			
		now a function of clear height and is			Updates code to recognize new
	Increased exit travel distances in Group F-				technology and marketplace
1017.2.2	-	vents	reduces	(\$100,000)	changes
				. /	
		Clarifies that minimum aisle width is a			

					Updates code to recognize new
		Reduced width allowed where bed or			technology and marketplace
1020.2	Corridor width in I-2 clarifications	stretcher movement is not necessary	reduces	(\$50,000)	changes
		Clarifies that no separation is			
		required between an exit stair and an			
1023.3.1	Stairway extensions	exit passageway	reduces	(\$10,000)	Improves code
		Inclusion of vehicle charging stations			Updates code to recognize new
	Accessible vehicle charging stations	into the accessibility requirements of			technology and marketplace
1107.2		the code.	adds	\$0	changes
		New exception for raised or lowered			
		areas in religious facilities. This topic			
	Raised and lowered areas in places of	has been the source of many variance			Improves current code, recognizes
1103.2.8	religious worship	applications	reduces	(\$20,000)	marketplace changes
		Significant improvement and			
		clarification to the vapor retarder			
		requirements for building envelopes			
		in Climate Zone 4 & 5 (Indiana). The			
		new codes incorporate the latest			
	Vapor retarder provisions revised	research and product technology for			
		this vitally important element. The			
		current Indiana code is outdated, and			
		allows practices that can create			
		serious mold and deterioration			Updates code to recognize new
		problems in a building.			technology and marketplace
1404.3			reduces	(\$500,000)	changes
		Updates regarding restroom privacy.			
		The commission has seen numerous			Improves current code, recognizes
		past variance applications related to			marketplace changes, closes
1210.3	Restroom privacy	this issue	adds	\$50,000	loopholes
		Adds provisions for the use of plastic			Updates code to recognize new
		composite materials and plastic		(\$400.000)	technology and marketplace
2612	Plastic composites	lumber Public toilet facilities no longer	reduces	(\$100,000)	changes
	Public toilet facilities in limited size,	required in such spaces (employee			Improves current code, recognizes
	quick service tenant spaces	toilet still required)	reduces	(\$100,000)	marketplace changes
		Adds options for providing multiple		(+	
		user facilities serving all genders.			Improves current code, recognizes
2902	Separate toilet facilities	Eliminates need for variances	reduces	(\$50,000)	marketplace changes
		All hoistway venting requirements			Updates code to recognize new
3004	Elevator hoistway venting	have been deleted	reduces	(\$100,000)	technology
		The use of intermodal shipping			
		containers as buildings and structures			Updates code to recognize new
2446	Intermedal chinging containers	is now allowed, and criteria defined for their use.	reduces	(\$50,000)	technology and marketplace
3115	Intermodal shipping containers			(\$50,000)	changes

Chapter 34 Chapter 34 deleted Numerous improvements to the structural code provisions in Chapter 16, incorporating the latest research. AIA Indiana also supports adoption of Chapter 17 of the model IBC and asks the Commission and its staff to facilitate any statutory changes necessary to allow	See analysis by Structural		Updates code to recognize new technology and marketplace changes
any statutory changes necessary to allow	See analysis by Structural Engineering Organization		
		(\$4,550,000)	