

Company		Mine
<b>Alliance Coal</b>		<b>Gibson County Coal South</b>
Inspection Date:	Thursday, April 4, 2024	
Areas Inspected:	1st North Belt and travelway, 1st NorthWest Belt and travelway, 1st NorthWest 2 Belt and Travelway	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	1st NW belt needs rock dusted or broomed, remove bad rollers from walkways and from under the belt.	
Inspection Date:	Monday, April 8, 2024	
Areas Inspected:	1st NorthWest Main Primary, 1st NorthWest Main intake	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	1st NorthWest Main Primary could use rock dusting again.	
Inspection Date:	Thursday, April 18, 2024	
Areas Inspected:	1 SW Main Belt and Intake, 1 SW Main 2 Belt and Intake	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	1 SWMain Belt could used rock dusting soon. The Belt shack on the 1SW Main needs dusted. Belt air needs attention at the end of the 1st SW 2.	
Inspection Date:	Thursday, April 25, 2024	
Areas Inspected:	Unit #3, New 1st SouthEast submain belt and travelway	
Findings / Law(s) Violated:	75.370(a)(1)	
Corrective Actions Taken:	Adjustments were made to the ventilation. Good job on maintaining belt air!	
Recommendation(s):	The curtain work on the unit needs tightened up. Stay on top of lifeline maintenance.	
Inspection Date:	Thursday, May 2, 2024	
Areas Inspected:	Slope Belt, 2 NorthWest Submain belt and intake	
Findings / Law(s) Violated:	The mine looked good	
Corrective Actions Taken:	None	
Recommendation(s):	Transfer points along the 2 NorthWest Submain belt need rock dusted.	
Inspection Date:	Thursday, May 9, 2024	
Areas Inspected:	Unit #2, Cr-8207, MCI8891, 2B12 Panel Intake and belt, 2A Panel Intake and belt	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	2A10 Panel intake and belt could use rock dusting.	

cont...

<b>Alliance Coal</b>	<b>Gibson County Coal South</b>
----------------------	---------------------------------

# Mine Inspection Reports

2nd Quarter

Inspection Date:	<b>Tuesday, May 14, 2024</b>
Areas Inspected:	<b>4A5 Belt and Intake, 4B12 Belt and Intake</b>
Findings / Law(s) Violated:	<b>None</b>
Corrective Actions Taken:	<b>None .. The mine looked good</b>
Recommendation(s):	<b>Keep conveyor belts properly trained, 4B12 panel belt XC-5-6 walkway needs widened. Continue adding support to corners that are falling off.</b>

Inspection Date:	<b>Thursday, June 13, 2024</b>
Areas Inspected:	<b>Unit #4</b>
Findings / Law(s) Violated:	<b>75.4</b>
Corrective Actions Taken:	<b>Management is addressing the issue</b>
Recommendation(s):	<b>Clean up needs to be better.</b>

Inspection Date:	<b>Wednesday, June 19, 2024</b>
Areas Inspected:	<b>Unit #1, MCI 8892, CR8230</b>
Findings / Law(s) Violated:	<b>75.811</b>
Corrective Actions Taken:	<b>The frame of the high voltage transmission line storage tub was properly grounded.</b>
Recommendation(s):	<b>None</b>

Inspection Date:	<b>Thursday, June 27, 2024</b>
Areas Inspected:	<b>2nd NW2 Submain belt and travelway, 1A6 Belt and travelway, CR8663</b>
Findings / Law(s) Violated:	<b>75.1403(5)(g)</b>
Corrective Actions Taken:	<b>The walkway is being cleared and belt cleaning is being addressed.</b>
Recommendation(s):	<b>2nd NW2 Submain belt needs cleaned from XC-53-55. 1A6 Belt needs spot cleaned.</b>

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

<b>Company</b>	<b>Mine</b>

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

cont...

Inspection Date:	
Areas Inspected:	

Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Company		Mine
Inspection Date:		
Areas Inspected:		

Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

cont...

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	

Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Company	Mine
<b>Peabody Midwest Mining</b>	<b>Francisco Mine</b>
Inspection Date:	Wednesday, April 3, 2024
Areas Inspected:	1 Main West Belt and travelway, 2 Main West belt and travelway, 3 Main West belt and travelway
Findings / Law(s) Violated:	75.1100-3

Corrective Actions Taken:	The fire extinguisher was examined and properly tagged.
Recommendation(s):	2 Main West belt needs shoveled on the intake side. Make sure B/O rollers are replaced.

Inspection Date:	Thursday, April 11, 2024
Areas Inspected:	3MW belt tail, 4MW Belt and travelway, 5MW Belt and travelway, BT5007, 5057, 5006, DVB 5109
Findings / Law(s) Violated:	75.400, 75.1403-5(g)
Corrective Actions Taken:	The coal was cleaned from the belt. Issues were addressed with management.
Recommendation(s):	Make repairs to 4MW belt, Rock dust 4MW belt from XC-85 to tail, keep belt structure off of the mine floor if it is functioning. 5MW belt need bridges built across intersection of XC-73

Inspection Date:	Tuesday, April 16, 2024
Areas Inspected:	1,2, and 3 West Left and right intakes
Findings / Law(s) Violated:	None
Corrective Actions Taken:	None
Recommendation(s):	None

Inspection Date:	Wednesday, April 24, 2024
Areas Inspected:	Unit #3
Findings / Law(s) Violated:	None
Corrective Actions Taken:	None
Recommendation(s):	Travelway from 9 West to Unit #3 needs some attention. The road is very rough.

Inspection Date:	Tuesday, April 30, 2024
Areas Inspected:	6 West Main Belt and travelway, 7 West Main Belt and travelway, MC5305, BT5110, BT5036, BT5019,
Findings / Law(s) Violated:	Looked Good!
Corrective Actions Taken:	None
Recommendation(s):	7 West belt needs rock dusted from air lock to XC-61, XC-61 needs better access path between Haulage and belt line. XC-70 to 71 walkway needs cleared.

Inspection Date:	Wednesday, May 8, 2024
Areas Inspected:	Unit #1
Findings / Law(s) Violated:	The Unit looked good!
Corrective Actions Taken:	None
Recommendation(s):	Temporary ventilation controls need tightened up.

cont...

<b>Peabody Midwest Mining</b>		<b>Francisco Mine</b>
Inspection Date:	Thursday, May 16, 2024	
Areas Inspected:	8 Main West Belt and travelway	
Findings / Law(s) Violated:	The areas looked good, BT5037, BT5012, BT5011	
Corrective Actions Taken:	None	

Recommendation(s):	<b>8MW belt XC-100-122 needs spot shoveled, , XC-130 to tail needs rock dusted, XC-146 Hog panel needs work in front of the mandoor leading to the intake.</b>
--------------------	--

Inspection Date:	<b>Wednesday, June 12, 2024</b>
Areas Inspected:	<b>8 Main West belt tail, 9 Main West Belt and travelway</b>
Findings / Law(s) Violated:	<b>75.400, 75.202(a)</b>
Corrective Actions Taken:	<b>The belt tail was cleared of accumulations, the area with loose roof bolts was dangered out and being addressed with management.</b>
Recommendation(s):	

Inspection Date:	<b>Monday, June 17, 2024</b>
Areas Inspected:	<b>Unit #3, UT5003, 4 Left Belt</b>
Findings / Law(s) Violated:	<b>75.370(a)(1), 75.400</b>
Corrective Actions Taken:	<b>Accumulations are being addressed, ventilation adjustments were made.</b>
Recommendation(s):	<b>Make sure that fire risers (hydrants) are able to be fully actuated. 4 left belt needs shoveled and rock dusted. Roads need work to unit #3</b>

Inspection Date:	<b>Monday, June 17, 2024</b>
Areas Inspected:	<b>Records</b>
Findings / Law(s) Violated:	<b>IC22-10-2-15(b)(1), IC22-10-2-15(b)(2)</b>
Corrective Actions Taken:	<b>The director made copies of the reports.</b>
Recommendation(s):	<b>None</b>

Inspection Date:	<b>Tuesday, June 25, 2024</b>
Areas Inspected:	<b>5th West SubMain Belt and travelway, 2 Left Panel Belt and travelway</b>
Findings / Law(s) Violated:	<b>75.1731(a), 75.1731(a)</b>
Corrective Actions Taken:	<b>The damaged rollers were marked for replacement, The conveyor belt was realigned.</b>
Recommendation(s):	<b>5th West Belt needs cleaned and rock dusted, both belt lined need to be trained to prevent component friction.</b>

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Company	Mine
<b>Peabody Midwest Mining</b>	<b>Francisco Mine</b>
Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	



Recommendation(s):	
--------------------	--

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

cont...

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Company	Mine
<b>Sunrise Coal</b>	<b>Oaktown Fuels #1 Mine</b>
Inspection Date:	Tuesday, April 2, 2024
Areas Inspected:	SE-4 Belt and travelway, SF-4 Belt and travelway, Battery charging station, SG-4 Belt and travelway
Findings / Law(s) Violated:	75.1731(a), 75.400, 75.809
Corrective Actions Taken:	The rollers were dropped and being replaced, A shovel crew was called for the belt, the belt drive motors were properly labeled.
Recommendation(s):	Keep transfer points rock dusted, SF4 and SG4 need shoveled, S-4 belt needs shoveled and dusted.

Inspection Date:	Tuesday, April 9, 2024
Areas Inspected:	SE-4, SF-4, SG-4 Intakes and right returns
Findings / Law(s) Violated:	The mine looked very good
Corrective Actions Taken:	None
Recommendation(s):	SG-4 intake XC-20 and 21 intake side of stoppings needs replastered.

Inspection Date:	Monday, April 15, 2024
Areas Inspected:	Production Unit #3, BT-5, S3-D Intake and return
Findings / Law(s) Violated:	75.333(b)(1)
Corrective Actions Taken:	The mine operator is addressing the issue.
Recommendation(s):	S3-D primary needs rock dust on the mine floor. Keep common areas common every 600 feet.

Inspection Date:	Monday, April 22, 2024
Areas Inspected:	M-15 Belt and Intake, M-16 Belt and Intake
Findings / Law(s) Violated:	None
Corrective Actions Taken:	None
Recommendation(s):	The belt-lines looked very good.

Inspection Date:	Monday, April 29, 2024
Areas Inspected:	M7 Belt and travelway, M10 Belt and travelway, DVB 4, BT 22, KDBB 03, LT 2, VCB 4, MC13, BT 25, T29
Findings / Law(s) Violated:	75.809
Corrective Actions Taken:	A temporary label was made for the cable
Recommendation(s):	M-7 belt needs dusted xc-55 to XC-67, XC-57 needs floor to roof support, M7 travelway to belt for access to mandoor, M10 Belt need dusted.

Inspection Date:	Monday, May 6, 2024
Areas Inspected:	Unit #4, KUT-10, P4-6 Itake, P4-6 Belt
Findings / Law(s) Violated:	None
Corrective Actions Taken:	
Recommendation(s):	P4-6 Intake Beginning to XC-F Needs dusted, P4-6 Belt Need to replace an SCSR in the Cache. The O2 reading was low.

cont...

<b>Sunrise Coal</b>	<b>Oaktown Fuels #1 Mine</b>
Inspection Date:	Wednesday, May 15, 2024
Areas Inspected:	M5 Belt and travelway, M5A Belt and travelway, M6 Belt and travelway, BT9, BT20, DVB14, BT11, BT21
Findings / Law(s) Violated:	75.202(a), 75.220(a)(1)
Corrective Actions Taken:	The issues are being corrected by the ine operator.
Recommendation(s):	M6 Belt XC-28-53 needs rock dusted, M6 XC-53 walkway to intake mandoor needs accessibility between the travelway and the beltline

Inspection Date:	Monday, June 3, 2024
Areas Inspected:	M6 Belt, Production unit #1, UT #3

Findings / Law(s) Violated:	<b>75.202(a), 75.220(a)(1), 75.1100-3</b>
Corrective Actions Taken:	<b>Areas have been dangered out and addressed with the mine operator</b>
Recommendation(s):	<b>XC-54 M6 belt the kettlebottom needs pryed down, curtain-work needs addressed on the unit, B.O&gt; Bolts and Kerr-Thobs need replaced with short bars or rails where the Kerr-Thob is out of compliance.</b>

Inspection Date:	<b>Thursday, June 20, 2024</b>
Areas Inspected:	<b>M-4 Belt and travelway, BT-21, KDBB=07, B7-13</b>
Findings / Law(s) Violated:	<b>75.333(b)(1)</b>
Corrective Actions Taken:	<b>The bad roof bolts were replaced with floor to roof support</b>
Recommendation(s):	<b>M4 Belt have several timbers, holding up rib rash, are broken and could be replaced.</b>

Inspection Date:	<b>Friday, June 14, 2024</b>
Areas Inspected:	<b>Unit #2</b>
Findings / Law(s) Violated:	<b>The unit looked good!</b>
Corrective Actions Taken:	<b>None</b>
Recommendation(s):	<b>None</b>

Inspection Date:	<b>Friday, June 28, 2024</b>
Areas Inspected:	<b>BT-1, KBT-32, KBT-38, KBT-39, T-8, BT-2, T-18, SC4 Travelway, Refuge chamber XC-32, M-3 Travelway</b>
Findings / Law(s) Violated:	<b>75.809, 75.601-1</b>
Corrective Actions Taken:	<b>The electrical issues were repaired by the mine operator.</b>
Recommendation(s):	<b>Keep a safe distance between moving equipment.</b>

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

<b>Company</b>	<b>Mine</b>
----------------	-------------

<b>Sunrise Coal</b>	<b>Oaktown Fuels #2 Mine</b>
Inspection Date:	<b>Thursday, March 28, 2024</b>
Areas Inspected:	<b>2nd South subMain seals, #rd Main South Seals, M4A seals</b>
Findings / Law(s) Violated:	<b>None</b>
Corrective Actions Taken:	<b>None</b>
Recommendation(s):	<b>None</b>

Inspection Date:	<b>Friday, April 5, 2024</b>
Areas Inspected:	<b>Unit #1, 1st East Submain Seals</b>

Findings / Law(s) Violated:	None
Corrective Actions Taken:	None
Recommendation(s):	Reset jacks under the Ziggy bars at XC-13 on the S1-2 travelway.

Inspection Date:	Wednesday, April 17, 2024
Areas Inspected:	M9 Intake and travelway, M10 Intake and travelway, M11 Intake and travelway, DVB10, LPDB01, LMC10
Findings / Law(s) Violated:	75.809
Corrective Actions Taken:	A temporary labeal was made for the cable
Recommendation(s):	None

Inspection Date:	Wednesday, May 1, 2024
Areas Inspected:	M8 Intake and travelway, KBT17, T7, DVB 08, LBT21
Findings / Law(s) Violated:	75.1100-3
Corrective Actions Taken:	The inspection was proerly performed and noted.
Recommendation(s):	None

Inspection Date:	Monday, May 13, 2024
Areas Inspected:	M7 Intake and travelway, M7A seals, T49, LUT03, LBT06
Findings / Law(s) Violated:	None
Corrective Actions Taken:	None
Recommendation(s):	M7 Intake and M7A seals could be rock dusted.

Inspection Date:	Monday, June 10, 2024
Areas Inspected:	Old Unit #1, S1-2 travelway
Findings / Law(s) Violated:	None
Corrective Actions Taken:	None
Recommendation(s):	None

cont...

<b>Sunrise Coal</b>	<b>Oaktown Fuels #2 Mine</b>
Inspection Date:	Tuesday, June 18, 2024
Areas Inspected:	M4 Intake and travelway, M6 Intake and travelway, T35, DVB13, LBT15, MC5, LBT10, LMC6
Findings / Law(s) Violated:	75.202(a)
Corrective Actions Taken:	The affected artea was dangered out.
Recommendation(s):	M6 intake needs floor to roof support XC45 - XC47.

Inspection Date:	Wednesday, June 26, 2024
Areas Inspected:	M2 Intake and travelway, M3 Intake panel and travelway, SCSR cache, BT8, LMC6, BT17, BT3
Findings / Law(s) Violated:	75.809

Corrective Actions Taken:	<b>A temporary label was attached to the cable.</b>
Recommendation(s):	<b>Make sure that changes underground are reflected on mine maps. M3 XC-5 5 rails need installed on belt side in the travelway. They area is flagged.</b>

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

<b>Company</b>	<b>Mine</b>
----------------	-------------

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	

Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

cont...

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	

Recommendation(s):	
--------------------	--

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

<b>Company</b>	<b>Mine</b>
----------------	-------------

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	



Recommendation(s):	
--------------------	--

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

cont...

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	