




1. Looking east at the eastern project terminus from the westbound shoulder of SR 32. Photo taken October 7, 2020.



2. Looking west at the surrounding landscape along the WB lanes of SR 32 just west of the farm field entrance. Photo taken October 7, 2020.

Lead Des No. 1800060 Appendix B: Graphics B54 of 210



3. Looking east from Enterprise Blvd. at the surrounding landscape along the EB lanes of SR 32. Photo taken October 8, 2020.



Looking west from Enterprise Blvd. at the surrounding landscape along the EB lanes of SR 32. Photo taken October 8, 2020.



5. Looking east at the surrounding landscape along the north side of SR 32 (WB lane) of SR 32. Photo taken October 7, 2020.



Looking west at the surrounding landscape along the north side of SR 32 (WB lane) of SR 32. Photo taken October 7, 2020.

Lead Des No. 1800060 Appendix B: Graphics B56 of 210



Looking west at the surrounding landscape along the south side of SR 32 (EB lane) of SR 32. Photo taken October 8, 2020.



Appendix B: Graphics

B57 of 210

Lead Des No. 1800060



Looking southeast from the EB shoulder of SR 32 at the CR S. 200 W. intersection. Photo taken October 8, 2021.



10. Looking west along the south side of SR 32 (EB lane) of SR 32 at the surrounding landscape. Photo taken July 6, 2021.



11. Looking east along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken July 6, 2021.



12. Looking west along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken July 6, 2021.



13. Looking east at the surrounding landscape along the south side of SR 32 (WB lane). Photo taken October 8, 2021.



14. Looking east along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken October 7, 2021.



15. Looking west along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken October 7, 2021.



16. Looking west along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken July 6, 2021.



Looking south at the outlet of the structure on the north side of SR 32 where Deer Creek originates. There will be no impacts to Deer Creek or this structure as part of this project. Photo taken October 7, 2020.



18. Looking north up Deer Creek from the outlet of the small diameter culvert pipe. Photo taken October 7, 2020.



Looking at a close up of the inlet side of small diameter culvert pipe. No stream channel or wetland feature was observed on the inlet side of the structure. No impacts to this structure will occur as a result of this project. Photo taken October 7, 2020.



20. Looking east along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken October 7, 2020.



21. Looking west along the north side of SR 32 (WB lane) and at the surrounding landscape. Photo taken October 7, 2020.



22. Looking east along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken October 8, 2020.



23. Looking west along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken October 8, 2020.



Looking west along the north side of SR 32 (WB lane) at Wetland A. No impacts to Wetland A will occur as a result of this project. Photo taken July 6, 2021.



25. Looking northwest along the east side of CR 250 W. at Wetland A. Photo taken July 6, 2021.



26. Looking northeast from the western boundary of Wetland B on the north side of SR 32 at a concrete headwall of a buried culvert pipe under CR 250 W. Photo taken October 7, 2020.



Looking west at Wetland B, which is located along the north side (WB lane) of SR 32. Note the mowed over cat-tails in 27. the photo. No impacts to Wetland B will occur as a result of this project. Photo taken October 7, 2020.



28. Looking southeast from CR 300 W. along the south side of SR 32 (EB lane). Photo taken October 8, 2020.



Looking northwest at the surrounding landscape, just west of CR 300 W. along the south side of SR 32 (EB lane). Photo 29. taken October 7, 2020.



30. Looking southeast along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken July 6, 2021.



31. Looking northwest along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken July 6, 2021.



32. Looking southeast along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken October 7, 2020.



33. Looking northwest along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken October 7, 2020.



34. Looking southeast along the south side of SR 32 (EB lane) from the CR 300 W. intersection. Photo taken October 8, 2020.



Looking northwest along the south side of SR 32 (EB lane) from the CR 300 W. intersection. Photo taken October 8, 35. 2020.



36. Looking southeast along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken July 6, 2021.



37. Looking northwest along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken July 6, 2021.





39. Looking northwest along the north side of SR 32 (WB lane) at the surrounding landscape and residential drive. Photo taken July 6, 2021.



40. Looking northwest along the south side (EB lane) of SR 32 at the surrounding landscape. Note the box culvert (CV 032-006-57.29) to the right of photo. This structure will not be impacted as part of this project. Photo taken October 7, 2020.




Looking southeast at the surrounding landscape towards CV 032-006-57.29 located on the north side of SR 32. Photo taken October 7, 2020.



42. Looking west along the EB lane of SR 32 from a residential drive at the surrounding landscape. Photo taken July 6, 2021.



Looking west along the north side of SR 32 (WB lane) just west of CR 325 W. at the surrounding landscape. This also 43. denotes the beginning of the first WB passing lane. Photo taken October 7, 2020.



44. Looking west along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken October 7, 2020.



Looking east along the south side of SR 32 (EB lane) from a shared residential/agricultural drive. Photo taken October 8, 2020.



Looking west along south side of SR 32 (EB lane) from a shared residential/agricultural drive. Photo taken October 8, 2020.

Lead Des No. 1800060 Appendix B: Graphics B76 of 210



47. Looking west at the surrounding landscape along the north side of SR 32 (WB lane). Photo taken October 7, 2020.



48. Looking west along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken July 6, 2021.



49. Looking west along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken July 6, 2021.





51. Looking west along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken October 7, 2020.





Looking east at the surrounding landscape along the north side of SR 32 (WB lane) just east of the CR 400 W. intersection. Photo taken July 6, 2021.



Looking west along the north side of SR 32 (WB lane) just west of the CR 400 W. intersection. Photo taken October 7, 2020.



Looking east/northeast along the south side of SR 32 (EB lane) from the CR 400 W. intersection. Photo taken October 8, 55. 2020.



56. Looking west along the south side of SR 32 (EB lane) from the CR 400 W. intersection. Photo taken October 8, 2020.



57. Looking east along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken October 7, 2020.





59. Looking east along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken July 6, 2021.



60. Looking west along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken July 6, 2021.



61. Looking east along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken July 6, 2021.



62. Looking west along the south side of SR 32 (EB lane) at the surrounding landscape. Photo taken July 6, 2021.



63. Looking east along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken July 6, 2021.



64. Looking west along the north side of SR 32 (WB lane) at the surrounding landscape. This also denotes the end of the first WB passing lane. Photo taken July 6, 2021.

Lead Des No. 1800060 Appendix B: Graphics B85 of 210



65. Looking east at the surrounding landscape located along the north side of SR 32 (WB lane) from just east of a residential drive. Photo taken October 7, 2020.



66. Looking west at the surrounding landscape located along the north side of SR 32 (WB lane). Photo taken October 7, 2020.



67. Looking west along the north side of SR 32 (WB lane) at the surrounding landscape. Photo taken October 7, 2020.

