

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 4/12/2012 Time: 10:44 AM  
Name of School Corporation: HAMILTON SOUTHEASTERN SCHOOLS Corp ID: 293005  
Address of School Corporation: 13485 Cumberland Rd  
City: Fishers Zip: 46038 County Number: 29  
VIN: 1HVBJAAR81A938018 License Number: 17918 Bus Number: 125  
Make of Body: AmTran Year: 2001 Make of Chassis: AmTran Year: 2001  
Bus Type: D Mileage: Unknown  
Inspection Status: O Inspected By: John Pang PE: 6196

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.
34-1-1	There is significant engine oil or fluid leak from the engine.
34-1-4	There is a significant fluid leak from the transmission.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
14-2-2	Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit.
14-2-6	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely.

### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.