

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 4/13/2012	<b>Time:</b> 8:16 AM
<b>Name of School Corporation:</b> HANOVER COMM. SCHOOL CORP.	<b>Corp ID:</b> 454580	
<b>Address of School Corporation:</b> 14525 Wicker		
<b>City:</b> Cedar Lake	<b>Zip:</b> 46303	<b>County Number:</b> 45
<b>VIN:</b> 1GDHG31FXX1050424	<b>License Number:</b> 19951	<b>Bus Number:</b> 24
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 1999	<b>Make of Chassis:</b> Blue Bird Corporation
<b>Year:</b> 1999	<b>Make of Chassis:</b> Blue Bird Corporation	<b>Year:</b> 1999
<b>Bus Type:</b>	<b>Mileage:</b> Unknown	
<b>Inspection Status:</b> R	<b>Inspected By:</b> Nathan Sherer	<b>PE:</b> 7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
36-1-6	Tailpipe does not extend to, or extends beyond the perimeter of the bus body.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------