

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Registration	<b>Date:</b>	2/21/2014	<b>Time:</b>	1:21 PM
<b>Name of School Corporation:</b>	SOUTHEAST FOUNTAIN SCHOOL CORP			<b>Corp ID:</b>	232455
<b>Address of School Corporation:</b>	744 E US 136				
<b>City:</b>	Veedersburg	<b>Zip:</b>	47987	<b>County Number:</b>	23
<b>VIN:</b>	1GB3G3BGXD1141117	<b>License Number:</b>	23529	<b>Bus Number:</b>	35
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2015	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>		<b>Mileage:</b>	Unknown	<b>Year:</b>	2013
<b>Inspection Status:</b>	A	<b>Inspected By:</b>	Nate King	<b>PE:</b>	7421

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------