

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |           |                         |           |
|---------------------------------------|--------------------------------|------------------------|-----------|-------------------------|-----------|
| <b>Type of Inspection:</b>            | Annual                         | <b>Date:</b>           | 5/5/2014  | <b>Time:</b>            | 1:14 PM   |
| <b>Name of School Corporation:</b>    | ATTICA CONSOLIDATED SCH. CORP. |                        |           | <b>Corp ID:</b>         | 232435    |
| <b>Address of School Corporation:</b> | 205 College St                 |                        |           |                         |           |
| <b>City:</b>                          | Attica                         | <b>Zip:</b>            | 47918     | <b>County Number:</b>   | 23        |
| <b>VIN:</b>                           | 1GBJG31U231188767              | <b>License Number:</b> | 58945     | <b>Bus Number:</b>      | 3         |
| <b>Make of Body:</b>                  | Mid Bus, Inc.                  | <b>Year:</b>           | 2003      | <b>Make of Chassis:</b> | Chevrolet |
| <b>Year:</b>                          | 2003                           | <b>Mileage:</b>        | Unknown   | <b>Year:</b>            | 2003      |
| <b>Bus Type:</b>                      |                                | <b>Mileage:</b>        | Unknown   |                         |           |
| <b>Inspection Status:</b>             | O                              | <b>Inspected By:</b>   | Nate King | <b>PE:</b>              | 7421      |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                                             |
|------------------------|--------------------------------------------------------------------------------|
| 15-1-1                 | There are leaks from the differential, pinion seal, or either rear wheel seal. |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>                                                                                                 |
|------------------------|--------------------------------------------------------------------------------------------------------------------|
| 8-2-1                  | There is no brake certification, the certification has expired, or is not signed within the six month requirement. |

### Bus Type Description