

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/11/2015	Time:	11:20 AM
Name of School Corporation:	SOUTH SPENCER CO. SCHOOL CORP.	Corp ID:	747445		
Address of School Corporation:	321 South 5th St				
City:	Rockport	Zip:	47635	County Number:	74
VIN:	4UZAAXCT84CM18547	License Number:	12635	Bus Number:	9
Make of Body:	Thomas Built Buses, Inc.	Year:	2004	Make of Chassis:	Freightliner
Bus Type:	C	Mileage:	103283		
Inspection Status:	O	Inspected By:	Mike Adams	PE:	7407

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-2	One (1) taillight or one (1) brake light does not function
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
31-2-1	Frame is deteriorated, cracked, broken or severely bent

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.