

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	3/1/2016	<b>Time:</b>	12:09 PM
<b>Name of School Corporation:</b>	NORTH LAWRENCE COMM. SCHOOLS	<b>Corp ID:</b>	475075		
<b>Address of School Corporation:</b>	595 Stars Blvd				
<b>City:</b>	Bedford	<b>Zip:</b>	47421	<b>County Number:</b>	47
<b>VIN:</b>	1GB0G2BG5B1164556	<b>License Number:</b>	NBNLHS40	<b>Bus Number:</b>	40
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2013	<b>Make of Chassis:</b>	Chevrolet
<b>Bus Type:</b>		<b>Mileage:</b>	99999999		
<b>Inspection Status:</b>	○	<b>Inspected By:</b>	Travis Coryea	<b>PE:</b>	5892

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

#### Inspection Code

#### Description

24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
24-2-2	Any body surface protrudes beyond the normal limits of the body structure

#### Bus Type Description