

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 4/14/2016	<b>Time:</b> 9:17 AM
<b>Name of School Corporation:</b> RICHLAND-BEAN BLOSSOM C.S.CORP	<b>Corp ID:</b> 535705	
<b>Address of School Corporation:</b> 600 S Edgewood Dr		
<b>City:</b> Ellettsville	<b>Zip:</b> 47429	<b>County Number:</b> 53
<b>VIN:</b> 1GDHG31R521213144	<b>License Number:</b> 63678	<b>Bus Number:</b> 52
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2002	<b>Make of Chassis:</b> GMC
<b>Year:</b> 2002	<b>Mileage:</b> 112382	<b>Year:</b> 2002
<b>Bus Type:</b>		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Mark Raper	<b>PE:</b> 6473

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
35-1-1	A heater motor is not operating properly
68-1-1	Washers do not function properly in any manner

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------