

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	11/1/2016	<b>Time:</b>	9:31 AM
<b>Name of School Corporation:</b>	RANDOLPH SOUTHERN SCHOOL CORP.			<b>Corp ID:</b>	686805
<b>Address of School Corporation:</b>	One Rebel Dr				
<b>City:</b>	Lynn	<b>Zip:</b>	47355	<b>County Number:</b>	68
<b>VIN:</b>	1FDXE45PX4HA92377	<b>License Number:</b>	40122	<b>Bus Number:</b>	22
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2006	<b>Make of Chassis:</b>	Ford
<b>Year:</b>		<b>Mileage:</b>	66158	<b>Year:</b>	2004
<b>Bus Type:</b>		<b>Inspected By:</b>	Jamie Hotchkiss	<b>PE:</b>	6458
<b>Inspection Status:</b>	O				

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
16-1-1	There are any leaks from the differential, pinion seal, or either rear wheel seal

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------