

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	9/13/2017	<b>Time:</b>	9:45 AM
<b>Name of School Corporation:</b>	AREA 30 CAREER CENTER			<b>Corp ID:</b>	676000
<b>Address of School Corporation:</b>	1 N Calbert Way Suite A				
<b>City:</b>	Greencastle	<b>Zip:</b>	46135	<b>County Number:</b>	67
<b>VIN:</b>	1GBJG31F221150648	<b>License Number:</b>	67769	<b>Bus Number:</b>	5
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2002	<b>Make of Chassis:</b>	Chevrolet
<b>Bus Type:</b>		<b>Mileage:</b>	79725	<b>Year:</b>	2002
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Tyler VanNess	<b>PE:</b>	7583

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
15-1-2	A defroster motor is inoperative at any speed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description