

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	2/5/2018	<b>Time:</b>	10:34 AM
<b>Name of School Corporation:</b>	SUNMAN-DEARBORN COMM. SCH CORP	<b>Corp ID:</b>	151560		
<b>Address of School Corporation:</b>	1 Trojan Place STE B				
<b>City:</b>	St Leon	<b>Zip:</b>	47012	<b>County Number:</b>	15
<b>VIN:</b>	1GDJG31K891157814	<b>License Number:</b>	77339	<b>Bus Number:</b>	SPVF
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2009	<b>Make of Chassis:</b>	GMC
<b>Year:</b>		<b>Year:</b>	2010		
<b>Bus Type:</b>		<b>Mileage:</b>	72786		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Chris Clark	<b>PE:</b>	6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-2	One (1) taillight or one (1) brake light does not function

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------