

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|--------------------------------|--------------------------------|-----------------|-----------|------------------|--------------------------|
| Type of Inspection: | Annual | Date: | 5/15/2018 | Time: | 10:48 AM |
| Name of School Corporation: | SOUTHEAST FOUNTAIN SCHOOL CORP | | | Corp ID: | 232455 |
| Address of School Corporation: | 744 E US 136 | | | | |
| City: | Veedersburg | Zip: | 47987 | County Number: | 23 |
| VIN: | 1GB3G3BGXD1141117 | License Number: | 23529 | Bus Number: | 35 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2013 | Make of Chassis: | Thomas Built Buses, Inc. |
| Bus Type: | | | | Mileage: | 41126 |
| Inspection Status: | R | Inspected By: | Nate King | PE: | 7421 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 23-1-5 | Any hanger, clamp or bracket is missing, loose or broken |

Violations - Out of Service

Inspection Code Description

Bus Type Description