

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |                 |                         |           |              |      |
|---------------------------------------|--------------------------------|------------------------|-----------------|-------------------------|-----------|--------------|------|
| <b>Type of Inspection:</b>            | Annual                         | <b>Date:</b>           | 5/15/2018       | <b>Time:</b>            | 12:59 PM  |              |      |
| <b>Name of School Corporation:</b>    | SOUTHEAST FOUNTAIN SCHOOL CORP |                        |                 | <b>Corp ID:</b>         | 232455    |              |      |
| <b>Address of School Corporation:</b> | 744 E US 136                   |                        |                 |                         |           |              |      |
| <b>City:</b>                          | Veedersburg                    | <b>Zip:</b>            | 47987           | <b>County Number:</b>   | 23        |              |      |
| <b>VIN:</b>                           | 1GB3GSBG6H1245541              | <b>License Number:</b> | 18013           | <b>Bus Number:</b>      | 30        |              |      |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.       | <b>Year:</b>           | 2017            | <b>Make of Chassis:</b> | Chevrolet | <b>Year:</b> | 2018 |
| <b>Bus Type:</b>                      |                                |                        | <b>Mileage:</b> | 24234                   |           |              |      |
| <b>Inspection Status:</b>             | A                              | <b>Inspected By:</b>   | Nate King       | <b>PE:</b>              | 7421      |              |      |

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

Bus Type Description