

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	6/25/2018	<b>Time:</b>	7:38 AM
<b>Name of School Corporation:</b>	MUNCIE COMMUNITY SCHOOLS	<b>Corp ID:</b>	181970		
<b>Address of School Corporation:</b>	2501 N Oakwood				
<b>City:</b>	Muncie	<b>Zip:</b>	47304	<b>County Number:</b>	18
<b>VIN:</b>	1GBJC31U471202688	<b>License Number:</b>	73848	<b>Bus Number:</b>	3
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2007	<b>Make of Chassis:</b>	Chevrolet
<b>Bus Type:</b>		<b>Mileage:</b>	81553		
<b>Inspection Status:</b>	<input type="radio"/>	<b>Inspected By:</b>	Jamie Hotchkiss	<b>PE:</b>	6458

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

#### Bus Type Description