REPORT OF SCHOOL BUS INSPECTION

Type of 8:58 Date: 12/18/2018 **Time**: Post-Crash Inspection Inspection: AM Name of School Corporation: STUDENT TRANSIT - RICHMOND Corp ID: 89001Z Address of School Corporation: 3175 Salisbury Rd N County City: Richmond Zip: 47374 89 Number: License VIN: RCS99 4UZABRFC6KCKN7066 **Bus Number:** 99 Number: Make of Thomas Built Buses, Year: 2018 Freightliner Year: Make of Body: 2019 Inc. Chassis: **Bus Type:** С Mileage: 6207 Inspected PE: 8139 **Inspection Status:** O Jeremy Mason By:

Violations - Rejected

Inspection Code	<u>Description</u>
57-1-5	Step-well light is missing or inoperative
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
53-1-3	Any spring hanger bushings or torque leaf bushings are worn, loose, broken or missing

Violations - Out of Service

Inspection Code	<u>Description</u>
36-2-1	The latch mechanism is missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.