

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	9/20/2019	<b>Time:</b>	8:55 AM
<b>Name of School Corporation:</b>	CULVER EDUCATIONAL FOUNDATION			<b>Corp ID:</b>	50001Z
<b>Address of School Corporation:</b>	1300 Academy Rd 154				
<b>City:</b>	Culver	<b>Zip:</b>	46511	<b>County Number:</b>	50
<b>VIN:</b>	1T7YU4A2591119266	<b>License Number:</b>	B536B	<b>Bus Number:</b>	1
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2008	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>		<b>Mileage:</b>	161841	<b>Year:</b>	2009
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Travis Harrold	<b>PE:</b>	8022

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

### Bus Type Description