

## REPORT OF SCHOOL BUS INSPECTION

|                                                                   |                                |                                   |
|-------------------------------------------------------------------|--------------------------------|-----------------------------------|
| <b>Type of Inspection:</b> Annual                                 | <b>Date:</b> 5/5/2020          | <b>Time:</b> 1:38 PM              |
| <b>Name of School Corporation:</b> SOUTHEAST FOUNTAIN SCHOOL CORP | <b>Corp ID:</b> 232455         |                                   |
| <b>Address of School Corporation:</b> 744 E US 136                |                                |                                   |
| <b>City:</b> Veedersburg                                          | <b>Zip:</b> 47987              | <b>County Number:</b> 23          |
| <b>VIN:</b> 1GB3G3BG8F1234334                                     | <b>License Number:</b> 35286   | <b>Bus Number:</b> 31             |
| <b>Make of Body:</b> Thomas Built Buses, Inc.                     | <b>Year:</b> 2015              | <b>Make of Chassis:</b> Chevrolet |
| <b>Bus Type:</b>                                                  | <b>Mileage:</b> 52346          | <b>Year:</b> 2015                 |
| <b>Inspection Status:</b> A                                       | <b>Inspected By:</b> Nate King | <b>PE:</b> 7421                   |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| <u>Bus Type</u> | <u>Description</u> |
|-----------------|--------------------|
|-----------------|--------------------|