

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 8/27/2020	<b>Time:</b> 9:46 AM
<b>Name of School Corporation:</b>	NORTH KNOX SCHOOL CORPORATION	<b>Corp ID:</b> 424315
<b>Address of School Corporation:</b>	11110 N SR 159	
<b>City:</b> Bicknell	<b>Zip:</b> 47512	<b>County Number:</b> 42
<b>VIN:</b> 1GB3G3BG4B1102858	<b>License Number:</b> 62829	<b>Bus Number:</b> 28
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2010	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2011	<b>Mileage:</b> 40301	
<b>Bus Type:</b>		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Bradley Miller	<b>PE:</b> 7809

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------