

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 9/21/2020	<b>Time:</b> 11:25 AM
<b>Name of School Corporation:</b> TRINITY LUTHERAN HIGH SCHOOL	<b>Corp ID:</b> 36B452	
<b>Address of School Corporation:</b> 7120 N CR 875 E		
<b>City:</b> Seymour	<b>Zip:</b> 47274	<b>County Number:</b> 36
<b>VIN:</b> 1GB3G2BGXF1246656	<b>License Number:</b> B433L	<b>Bus Number:</b> 2
<b>Make of Body:</b> Chevrolet	<b>Year:</b> 2015	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2015	<b>Bus Type:</b>	<b>Mileage:</b> 43965
<b>Inspection Status:</b> O	<b>Inspected By:</b> Travis Coryea	<b>PE:</b> 5892

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
79-1-3	If equipped the emergency warning buzzer does not sound

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-4	Emergency door is not securely fastened to body

### Bus Type Description