

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 4/15/2021	<b>Time:</b> 10:34 AM
<b>Name of School Corporation:</b> TRI-COUNTY SCHOOL CORPORATION	<b>Corp ID:</b> 918535	
<b>Address of School Corporation:</b>		
<b>City:</b>	<b>Zip:</b>	<b>County Number:</b> 91
<b>VIN:</b> 1HVBBAANX4H673706	<b>License Number:</b> 9387	<b>Bus Number:</b> 15
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2004	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2004	<b>Mileage:</b> 157108	<b>PE:</b> 7421
<b>Inspection Status:</b> O	<b>Inspected By:</b> Nate King	

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
18-2-3	Center/carrier bearing: any broken or loose center/carrier bearing bracket, bolts or mounting hardware, any center bearing bracket crack equaling fifty (50) percent or more of the original width, more than one half (1/2) inch vertical movement of the shaft in the center bearing carrier (rubber)

#### Bus Type Description