

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|-------------------------------------|------------------------|-----------------|-------------------------|-----------|--------------|------|
| Type of Inspection: | Re-Inspection | Date: | 6/22/2021 | Time: | 10:12 AM | | |
| Name of School Corporation: | OLD NATIONAL TRAIL SPECIAL SERVICES | | | Corp ID: | 530001 | | |
| Address of School Corporation: | | | | | | | |
| City: | | Zip: | | County Number: | 67 | | |
| VIN: | 1GB3G3BG2B1151962 | License Number: | 9454 | Bus Number: | 2 | | |
| Make of Body: | Collins Bus Corporation | Year: | 2011 | Make of Chassis: | Chevrolet | Year: | 2011 |
| Bus Type: | | | Mileage: | 22217 | | | |
| Inspection Status: | R | Inspected By: | Byron Goodman | PE: | 7008 | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 23-1-10 | The exhaust system is not properly installed |
| 23-1-9 | Tailpipe has been reduced in a size (diameter) from the rear of the muffler |
| 23-1-11 | Any tailpipe exits beneath an emergency door |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| <u>Bus Type</u> | <u>Description</u> |
|-----------------|--------------------|
|-----------------|--------------------|