

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 11/10/2021	Time: 2:07 PM
Name of School Corporation: RICHLAND-BEAN BLOSSOM C.S.CORP	Corp ID: 535705	
Address of School Corporation: 600 S Edgewood Dr		
City: Ellettsville	Zip: 47429	County Number: 53
VIN: 4DRBUAFN75B979917	License Number: 20509a	Bus Number: 40
Make of Body: IC Corporation	Year: 2004	Make of Chassis: IC Corporation
Year: 2005	Mileage: 230432	
Bus Type: C		PE: 6473
Inspection Status: O	Inspected By: Mark Raper	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-1	Any headlight is inoperative
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
31-2-1	Frame is deteriorated, cracked, broken or severely bent
55-2-6	Steering box is loose on the frame
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.