

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|--------------------------------|------------------------|-----------------|-------------------------|-----------|--------------|------|
| Type of Inspection: | Annual | Date: | 4/6/2022 | Time: | 1:35 PM | | |
| Name of School Corporation: | SOUTHEAST FOUNTAIN SCHOOL CORP | | | Corp ID: | 232455 | | |
| Address of School Corporation: | 744 E US 136 | | | | | | |
| City: | Veedersburg | Zip: | 47987 | County Number: | 23 | | |
| VIN: | 1GB3G3BG0F1232514 | License Number: | 33764 | Bus Number: | 32 | | |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2015 | Make of Chassis: | Chevrolet | Year: | 2016 |
| Bus Type: | | | Mileage: | 65366 | | | |
| Inspection Status: | R | Inspected By: | Nate King | PE: | 7421 | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 23-1-5 | Any hanger, clamp or bracket is missing, loose or broken |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

Bus Type Description