

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 4/6/2022	<b>Time:</b> 1:35 PM
<b>Name of School Corporation:</b> SOUTHEAST FOUNTAIN SCHOOL CORP	<b>Corp ID:</b> 232455	
<b>Address of School Corporation:</b> 744 E US 136		
<b>City:</b> Veedersburg	<b>Zip:</b> 47987	<b>County Number:</b> 23
<b>VIN:</b> 1GB3G3BG0F1232514	<b>License Number:</b> 33764	<b>Bus Number:</b> 32
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2015	<b>Make of Chassis:</b> Chevrolet
		<b>Year:</b> 2016
<b>Bus Type:</b>	<b>Mileage:</b> 65366	
<b>Inspection Status:</b> R	<b>Inspected By:</b> Nate King	<b>PE:</b> 7421

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------