

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	8/23/2022	<b>Time:</b>	8:52 AM
<b>Name of School Corporation:</b>	WASHINGTON COMM. SCHOOLS, INC.	<b>Corp ID:</b>	141405		
<b>Address of School Corporation:</b>	301 E South St				
<b>City:</b>	Washington	<b>Zip:</b>	47501	<b>County Number:</b>	14
<b>VIN:</b>	1GB6G3AG1A1152923	<b>License Number:</b>	1801	<b>Bus Number:</b>	A1
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2010	<b>Make of Chassis:</b>	Chevrolet
<b>Bus Type:</b>		<b>Year:</b>	2011	<b>Mileage:</b>	80907
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Philip Lubbers	<b>PE:</b>	7703

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

### Violations - Out of Service

Inspection Code Description

Bus Type Description