

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	10/31/2022	<b>Time:</b>	9:47 AM
<b>Name of School Corporation:</b>	EVANSVILLE-VANDERBURGH SCH COR			<b>Corp ID:</b>	827995
<b>Address of School Corporation:</b>	951 Walnut St				
<b>City:</b>	Evansville	<b>Zip:</b>	47713	<b>County Number:</b>	82
<b>VIN:</b>	1T7YU4E22C1144286	<b>License Number:</b>	4862	<b>Bus Number:</b>	T5
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2010	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>		<b>Mileage:</b>	216275	<b>Year:</b>	2012
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Bradley Miller	<b>PE:</b>	7809

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
7-1-2	ABS warning light is illuminated
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

### Bus Type Description