

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Semi-Annual  
**Name of School Corporation:** DALEVILLE COMMUNITY SCHOOLS  
**Address of School Corporation:** 14300 W 2nd St  
**City:** Daleville  
**VIN:** 1GBHG31R6Y1119579  
**Make of Body:** Thomas Built Buses, Inc.  
**Bus Type:**  
**Inspection Status:** R

**Date:** 11/29/2022  
**Time:** 11:19 AM  
**Corp ID:** 181940  
**Zip:** 47334  
**County Number:** 18  
**License Number:** 6972  
**Bus Number:** 21  
**Make of Chassis:** Chevrolet  
**Year:** 1999  
**Year:** 2000  
**Mileage:** 60765  
**Inspected By:** Steve Spallinger  
**PE:** 6921

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
20-1-7	If bus manufactured after 5-2-1994, one (1) inch reflective tape is not applied to the door outline, is missing, or badly faded (two (2) is permissible on bumper below door if insufficient space on body

### Violations - Out of Service

Inspection Code Description

Bus Type Description