

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|------------------------------|------------------------|-----------------|-------------------------|-----------|
| Type of Inspection: | Re-Inspection | Date: | 2/13/2023 | Time: | 11:20 AM |
| Name of School Corporation: | TRINITY LUTHERAN HIGH SCHOOL | Corp ID: | 36B452 | | |
| Address of School Corporation: | 7120 N CR 875 E | | | | |
| City: | Seymour | Zip: | 47274 | County Number: | 36 |
| VIN: | 1GB3G2BG5D1166114 | License Number: | B955h | Bus Number: | 1 |
| Make of Body: | Starcraft | Year: | 2013 | Make of Chassis: | Chevrolet |
| Year: | 2013 | | Mileage: | 86258 | |
| Inspection Status: | O | Inspected By: | Seth Davidson | PE: | 8101 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------------------------------------------------------|
| 62-1-9 | LED type lights have 25% to 49% pixels inoperable in any one light |
| 62-1-2 | One (1) taillight or one (1) brake light does not function |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|-------------------------------------------------|
| 64-2-1 | Any rear turn signal does not function properly |

Bus Type Description