

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	6/15/2023	<b>Time:</b>	9:54 AM		
<b>Name of School Corporation:</b>	SOUTHEAST FOUNTAIN SCHOOL CORP			<b>Corp ID:</b>	232455		
<b>Address of School Corporation:</b>	744 E US 136						
<b>City:</b>	Veedersburg	<b>Zip:</b>	47987	<b>County Number:</b>	23		
<b>VIN:</b>	1GB3G3BGXD1141117	<b>License Number:</b>	23529	<b>Bus Number:</b>	35		
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2013	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2013
<b>Bus Type:</b>		<b>Mileage:</b>	74476				
<b>Inspection Status:</b>	A	<b>Inspected By:</b>	Nate King	<b>PE:</b>	7421		

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

Bus Type Description