

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Semi-Annual	<b>Date:</b> 8/22/2023	<b>Time:</b> 8:36 AM	
<b>Name of School Corporation:</b> WASHINGTON CATHOLIC SCHOOLS	<b>Corp ID:</b> 14A664		
<b>Address of School Corporation:</b> 201 N.E. 2nd St			
<b>City:</b> Washington	<b>Zip:</b> 47501	<b>County Number:</b> 14	
<b>VIN:</b> 1GBJG31U961150747	<b>License Number:</b> B929AD	<b>Bus Number:</b> 21	
<b>Make of Body:</b> Mid Bus, Inc.	<b>Year:</b> 2005	<b>Make of Chassis:</b> Chevrolet	<b>Year:</b> 2006
<b>Bus Type:</b>	<b>Mileage:</b> 91531		
<b>Inspection Status:</b> <input type="radio"/>	<b>Inspected By:</b> Philip Lubbers	<b>PE:</b> 7703	

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

#### Bus Type Description