

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/5/2023	Time:	8:59 AM
Name of School Corporation:	SOUTH SPENCER CO. SCHOOL CORP.	Corp ID:	747445		
Address of School Corporation:	321 South 5th St				
City:	Rockport	Zip:	47635	County Number:	74
VIN:	1GB3G3BG1C1120042	License Number:	12260	Bus Number:	25
Make of Body:	Thomas Built Buses, Inc.	Year:	2011	Make of Chassis:	Chevrolet
Year:		Year:		Year:	2012
Bus Type:		Mileage:	56380		
Inspection Status:	<input type="radio"/>	Inspected By:	Philip Lubbers	PE:	7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description