## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual			Date:	2/13/2024	Time:	9:10 AM
Name of School Corporation:		SOU	OUTH SPENCER CO. SCHOOL CORP.			Corp ID:	747445
Address of School Corporation:			321 South 5th St				
City:	Rockport		Zip:	47635		County Number:	74
VIN:	4UZABRDU1GCHF58	38		License Number:	10372	Bus Number:	13
Make of Body:	Thomas Built Buses, Inc.	Year:	: 2015	Make of Chassis:	Freightliner	Year:	2016
Bus Type:	С			Mileage:	88753		
Inspection Status	: R		Inspected By:	Philip Lubbers		PE:	7703

## **Violations - Rejected**

Inspection Code	Description
50-1-3	The seat belt cutter is contained in a compartment.
50-1-2	The seat belt cutter is not secured using a positive fastening method.

## **Violations - Out of Service**

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.