

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	4/18/2024	<b>Time:</b>	5:13 PM
<b>Name of School Corporation:</b>	AREA 30 CAREER CENTER	<b>Corp ID:</b>	676000		
<b>Address of School Corporation:</b>	1 N Calbert Way Suite A				
<b>City:</b>	Greencastle	<b>Zip:</b>	46135	<b>County Number:</b>	67
<b>VIN:</b>	1GBJG31F221150648	<b>License Number:</b>	67769	<b>Bus Number:</b>	5
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2002	<b>Make of Chassis:</b>	Chevrolet
<b>Bus Type:</b>		<b>Mileage:</b>	81141	<b>Year:</b>	2002
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Byron Goodman	<b>PE:</b>	7008

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description