

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	10/20/2025	<b>Time:</b>	9:23 AM
<b>Name of School Corporation:</b>	WESTFIELD-WASHINGTON SCHOOLS	<b>Corp ID:</b>	293030		
<b>Address of School Corporation:</b>	17303 Ditch Rd				
<b>City:</b>	Westfield	<b>Zip:</b>	46074	<b>County Number:</b>	29
<b>VIN:</b>	1GB3G3BG9B1111295	<b>License Number:</b>	7742	<b>Bus Number:</b>	A1
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2010	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>		<b>Year:</b>		<b>Year:</b>	2011
<b>Bus Type:</b>		<b>Mileage:</b>	127951		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Nathan Hampton	<b>PE:</b>	8616

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
10-2-2	The parking brake fails to hold the bus during the testing procedure. (Note – It is NOT a violation if the test cannot be done due to OEM design)

#### Bus Type Description