

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	04/16/2020	Time:	1:36 PM
Name of School Corporation:	SOUTHWEST PARKE COMM SCH CORP			Corp ID:	616260
Address of School Corporation:	RR 1				
City:	Montezuma	Zip:	47862	County Number:	61
VIN:	4DRBUAAP6DB163921	License Number:	14643	Bus Number:	SWP14
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation
		Year:		Year:	2013
Bus Type:	4	Mileage:	53937		
Comments:					
Inspection Status:	Out of Service	Inspected By:	Byron Goodman	PE:	7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>	<u>Comments</u>
65-1-6	LED Lights have 25% to 49% of pixels inoperable.	

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>	<u>Comments</u>
------------------------	--------------------	-----------------