

1200 New Jersey Ave., SE Washington, D.C. 20590

February 10, 2016

In Reply Refer To: HSST/ B-258

Mr. John Wright Indiana Department of Transportation 100 N. Senate Ave. Indianapolis, IN 46204

Dear Mr. Wright:

This letter is in response to your September 3, 2015 request for the Federal Highway Administration (FHWA) to review a roadside safety device, hardware, or system for eligibility for reimbursement under the Federal-aid highway program. This FHWA letter of eligibility is assigned FHWA control number B-258 and is valid until a subsequent letter is issued by FHWA that expressly references this device.

Decision

The following devices are eligible, with details provided in the form which is attached as an integral part of this letter:

• Indiana Anchored Temporary Concrete Barrier

Scope of this Letter

To be found eligible for Federal-aid funding, new roadside safety devices should meet the crash test and evaluation criteria contained in the American Association of State Highway and Transportation Officials' Manual for Assessing Safety Hardware (MASH). However, the FHWA, the Department of Transportation, and the United States Government do not regulate the manufacture of roadside safety devices. Eligibility for reimbursement under the Federal-aid highway program does not establish approval, certification or endorsement of the device for any particular purpose or use.

This letter is not a determination by the FHWA, the Department of Transportation, or the United States Government that a vehicle crash involving the device will result in any particular outcome, nor is it a guarantee of the in-service performance of this device. Proper manufacturing, installation, and maintenance are required in order for this device to function as tested.

This finding of eligibility is limited to the crashworthiness of the system and does not cover other structural features, nor conformity with the Manual on Uniform Traffic Control Devices.

Eligibility for Reimbursement

Based solely on a review of crash test results and certifications submitted by the manufacturer, and the crash test laboratory, FHWA agrees that the device described herein meets the crash test and evaluation criteria of the American Association of State Highway and Transportation Officials' Manual for Assessing Safety Hardware (MASH). Therefore, the device is eligible for reimbursement under the Federal-aid highway program if installed under the range of tested conditions.

Name of system: Indiana Anchored Temporary Concrete Barrier
Type of system: Precast concrete F-Shape barrier, using J-J Hook

connection, bent angle plates at third points of each barrier

unit, wedge anchor studs, and bolt down top plates

Test Level: MASH Test Level 3

Testing conducted by: Texas Transportation Institute

Task Force 13 Designator: NA

Date of request: September 3, 2015
Date initially acknowledged: October 21, 2015
Date of completed package: February 2, 2016

FHWA concurs with the recommendation of the accredited crash testing laboratory as stated within the attached form.

Full Description of the Eligible Device

The device and supporting documentation, including reports of the crash tests or other testing done, videos of any crash testing, and/or drawings of the device, are described in the attached form.

Notice

If a manufacturer makes any modification to any of their roadside safety hardware that has an existing eligibility letter from FHWA, the manufacturer must notify FHWA of such modification with a request for continued eligibility for reimbursement. The notice of all modifications to a device must be accompanied by:

- o Significant modifications For these modifications, crash test results must be submitted with accompanying documentation and videos.
- Non-signification modifications For these modifications, a statement from the crash test laboratory on the potential effect of the modification on the ability of the device to meet the relevant crash test criteria.

FHWA's determination of continued eligibility for the modified hardware will be based on whether the modified hardware will continue to meet the relevant crash test criteria.

You are expected to supply potential users with sufficient information on design, installation and maintenance requirements to ensure proper performance.

You are expected to certify to potential users that the hardware furnished has the same chemistry, mechanical properties, and geometry as that submitted for review, and that it will meet the test and evaluation criteria of the MASH.

Issuance of this letter does not convey property rights of any sort or any exclusive privilege. This letter is based on the premise that information and reports submitted by you are accurate and correct. We reserve the right to modify or revoke this letter if: (1) there are any inaccuracies in the information submitted in support of your request for this letter, (2) the qualification testing was flawed, (3) in-service performance or other information reveals safety problems, (4) the system is significantly different from the version that was crash tested, or (5) any other information indicates that the letter was issued in error or otherwise does not reflect full and complete information about the crashworthiness of the system.

Standard Provisions

- To prevent misunderstanding by others, this letter of eligibility designated as FHWA
 control number B-258 shall not be reproduced except in full. This letter and the test
 documentation upon which it is based are public information. All such letters and
 documentation may be reviewed upon request.
- This letter shall not be construed as authorization or consent by the FHWA to use, manufacture, or sell any patented system for which the applicant is not the patent holder.
- If the subject device is a patented product it may be considered to be proprietary. If proprietary systems are specified by a highway agency for use on Federal-aid projects:

 (a) they must be supplied through competitive bidding with equally suitable unpatented items; (b) the highway agency must certify that they are essential for synchronization with the existing highway facilities or that no equally suitable alternative exists; or (c) they must be used for research or for a distinctive type of construction on relatively short sections of road for experimental purposes.

Our regulations concerning proprietary products are contained in Title 23, Code of Federal Regulations, Section 635.411.

Sincerely yours,

Michael S. Griffith

Director, Office of Safety Technologies

Michael S. Fufforth

Office of Safety

Enclosures

Request for Federal Aid Reimbursement Eligibility of Highway Safety Hardware

| | Date of Request: | September 03, 2015 | New | | | | | | |
|-----------|------------------|---|-----|--|--|--|--|--|--|
| | Name: | | | | | | | | |
| ter | Company: | Company: Indiana Department of Transportation | | | | | | | |
| Submitter | Address: | 100 N. Senate Ave., Indianapolis, IN 46204 | | | | | | | |
| Sub | Country: | USA | | | | | | | |
| | То: | Michael S. Griffith, Director FHWA, Office of Safety Technologies | | | | | | | |

I request the following devices be considered eligible for reimbursement under the Federal-aid highway program.

| e e | | | [1-1-1] | |
|--|-------------------------------|---|-------------------|---------------|
| System Type | Submission Type | Device Name / Variant | Testing Criterion | Test Level |
| 'B': Barriers (Roadside, Median, Bridge Railings) | I (A LIIAZICUI CIUZII I CAMIN | Indiana Temporary Anchored Concrete Barrier | AASHTO MASH | TL3 |

By submitting this request for review and evaluation by the Federal Highway Administration, I certify that the product(s) was (were) tested in conformity with the AASHTO Manual for Assessing Safety Hardware and that the evaluation results meet the appropriate evaluation criteria in the MASH.

Identification of the individual or organization responsible for the product:

| Contact Name: | John Wright | Same as Submitter 🔀 |
|---------------|--|-------------------------------|
| Company Name: | Indiana Department of Transportation | Same as Submitter 🛛 |
| Address: | 100 N. Senate Ave., Indianapolis, IN 46204 | Same as Submitter 🛛 |
| Country: | USA | Same as Submitter 🔀 |
| | isclosures of financial interests as required by the FH for Safety Hardware Devices' document. | WA `Federal-Aid Reimbursement |

In regard to the Indiana DOT Temporary Anchored Concrete Barrier, TTI Proving Ground had/has no financial interests. Indiana DOT contracted for the service of crash testing this barrier according to specifications for American Association of State Highway and Transportation Officials (AASHTO) Manual for Assessing Safety Hardware (MASH) Test 3-11, for which TTI Proving Ground was compensated for the cost to perform the test. No consulting relationships, research funding or other forms of research support, patents, copyrights, other intellectual property interests, licenses, contractual relationships, business ownership or investment interests are retained for the TTI Proving Ground.

PRODUCT DESCRIPTION

| | | |
|--|-----------------------------------|--|
| ew Hardware or gnificant Modification | Modification to Existing Hardware | |
| • | | |

INDOT conducted three tests for this Temporary Anchored Concrete Barrier system. All three tests used a standard 31 inch F-shape concrete barrier. Each barrier segment was 10 ft long, 31 inches tall and 24 inches wide at the bottom, tapering to 10 inches wide at the top. Due to different barrier wall suppliers, some barriers had a 3 inch reveal and some had a 2 inch reveal. Placement of those segments are detailed in each report. All barrier used J-J hooks for connection.

Test 1 (Test Report # 690900-IND1) – conducted Jan. 8th, 2015. This test utilized a 90° bent angle plate at each joint. This test failed and is not part of this request. Photos, video and the report are attached for viewing purposes. This was the barrier that Indiana currently uses and had been used for some time with no reported flaws.

Test 2 (Test Report # 690900-IND2) – conducted April 16th, 2015. This test utilized three bent angle plates per barrier and a 4 bolt top plate recessed into the barrier. The top plate holes were formed into the concrete using ferrule loops as discussed in the report. The test passed but we noticed a construction problem where it was hard to line up the 4 top plate bolts due to variances in the J-J hook installation. Also the ferrule loops were poured into the concrete barrier, so could not use existing temporary barrier and convert it into the anchor barrier, so, we preceded with a third test.

Test 3 (Test Report # 690900-IND3) – conducted May 19th, 2015. This test utilized three bent angle plates per barrier and a 2 bolt top plate connecting the barriers that were not recessed. The top plate holes were predrilled and expansion anchors were inserted as discussed in the report. Note that the top plate bolts were tightened with no specific torque value.

CRASH TESTING

A brief description of each crash test and its result:

| | | Page 3 of 5 |
|-------------------------|---|-----------------------------|
| Required Test Number | Narrative Description | Evaluation Results |
| | For anchored precast barrier systems, MASH Test 3-11 (2270 kg. Pickup @ 100 km/hr @ 25 degrees impact angle), which was performed for this project, is the critical test for barrier strength. Mash Test 3-10 (1100 kg small car @ 100 km/hr @ 25 degrees impact angle) is critical for vehicle stability and occupant risk. For MASH Test 3-10, and anchored barrier like the one tested for this project, the barrier lateral deflection is typically small and the barrier behaves more like a rigid barrier. | |
| | A rigid New Jersey Barrier has been successfully tested to MASH 3-10 Specification (see Midwest Roadside Safety Facility Test Report 2214NJ-1). Other successful small car tests were reported on the F-Shape Barrier and New Jersey Safety Shape barrier. They are referenced as follows: | |
| 3-10 (1100C) | 1.) TTI no. 7069-3 reported in two volumes FHWA-RD93-058, "Testing of New Bridge Rail and Transitions Designs, Volume 1: Technical Report "FHWA-RD-93-064 "testing of New Bridge Rail and Transition Designs Volume 7: Appendix F 32-inch (813-mm) F-Shape Bridge Railing". 2.) 42-inch Safety Shape Test with Small Car – TTI Test No. 4348-1 reported in "Development of High-Performance Median Barrier" | Non-Critical, not conducted |
| | For Test Report 2214NJ-1, the safety shape barrier was impacted by a 2579-lb passenger car at 60.8 mph and 26.1 degrees impact angle. This test was successful with respect to MASH criteria. While MASH Test 3-10 has not been performed to date on a rigid F-Shape barrier, the F-Shape has been successfully tested with an 817 kg. small car at 60 mph and 21.4 degrees impact angle and reported in Project 7069-3 herein. A comparable test on the New Jersey Shape was performed at a lesser 15 degree impact angle and reported in Project 4348-1 (843 kg. small car at 62.6 mph at 15.0 degrees impact angle). This test was also deemed successful. | |
| | TTI has reviewed the data summaries for the small car tests provided herein on the F-Shape and New Jersey Shape. Based on the results of these tests, the F-Shape performed better for the small cars tests (more stable) even with a higher impact angle. Therefore, under the MASH guidelines, the F-Shape should perform better than the New Jersey Shape barrier which has been successfully tested to MASH. Therefore, the MASH Test 3-10 was deemed unnecessary for this testing. | |

| | | 1090 1 01 3 |
|-------------------------|---|-----------------------------|
| Required Test Number | Narrative Description | Evaluation Results |
| 3-11 (2270P) | TL-3 test of a 31 inch F-shape concrete barrier. Each barrier segment was 10 ft long, 31 inches tall and 24 inches wide at the bottom, tapering to 10 inches wide at the top. Test 1 (Test Report # 690900-IND1) – report submitted for viewing purposes only. Test 2 (Test Report # 690900-IND2) – The Indiana Anchored Temporary Barrier with wedge anchor studs contained and redirected the 2270P vehicle. Maximum dynamic deflection during the test was 11.9 inches. Maximum occupant impact velocity and subsequent ride down accelerations were 15.1 ft/s longitudinal OIV, 24.6 ft/s lateral OIV and 5.1 G longitudinal RDA and 11.2 G lateral RDA. No deformation or intrusion of the occupant compartment occurred. The 2270P vehicle remained upright during and after the collision event. Maximum roll was 18° and maximum pitch was 18°. Occupant risk factors are within limits specified in MASH. The test was successful for a TL-3 crash test. Test 3 (Test Report # 690900-IND3) – The Indiana Anchored Temporary Barrier with wedge anchor studs contained and redirected the 2270P vehicle. Maximum dynamic deflection during the test was 13.3 inches. Maximum occupant impact velocity and subsequent ride down accelerations were 16.7 ft/s longitudinal OIV, 24.3 ft/s lateral OIV and 8.9 G longitudinal RDA and 10.8 G lateral RDA. No detached elements, fragments or other debris was present to penetrate or to show potential for penetrating the occupant department, or to present hazzard to others in the area. The 2270P vehicle remained upright during and after the collision event. Maximum roll was 26° and maximum pitch was 25°. Occupant risk factors are within limits specified in MASH. The test was successful for a TL-3 crash test. | PASS |
| 3-20 (1100C) | Not relevant, transition not tested for this system | Non-Critical, not conducted |
| 3-21 (2270P) | Not relevant, transition not tested for this system | Non-Critical, not conducted |

Full Scale Crash Testing was done in compliance with MASH by the following accredited crash test laboratory (cite the laboratory's accreditation status as noted in the crash test reports.):

| Laboratory Name: | Texas Transportation Institute | |
|--|--|-------------------|
| Laboratory Signature: | charld in | |
| Address: | Roadside Safety & Physical Security Texas A&M University System 3135 TAMU College Station, TX 77843-3135 | Same as Submitter |
| Country: | USA | Same as Submitter |
| Accreditation Certificate Number and Dates of current Accreditation period : | ISO 17025 Laboratory Testing Certificate # 3821.01 Accreditation date 02/19/2015 through 04-30/2017 | |

Submit Form


ATTACHMENTS

Attach to this form:


- 1) Additional disclosures of related financial interest as indicated above.
- 2) A copy of the full test report, video, and a Test Data Summary Sheet for each test conducted in support of this request.
- 3) A drawing or drawings of the device(s) that conform to the Task Force-13 Drawing Specifications [Hardware Guide Drawing Standards]. For proprietary products, a single isometric line drawing is usually acceptable to illustrate the product, with detailed specifications, intended use, and contact information provided on the reverse. Additional drawings (not in TF-13 format) showing details that are relevant to understanding the dimensions and performance of the device should also be submitted to facilitate our review.


FHWA Official Business Only:

| Eligibility Letter | | AASHTO TF13 | | |
|--------------------|--|-------------|-----------|--|
| Number Date | | Designator | Key Words | |
| | | | | |



- 1a. Nominal concrete apron thickness. Actual thickness may be up to 1" greater or less.
- **1b.** Install Wedge Anchors according to manufacturer's instructions with 4-1/2" embedment. Two at each Bracket. Tighten to 250ft/lbs (minimum according to manufacturer's specifications).
- 1c. Barriers 1 4 and 15 20 were used in a previous test. Barriers 5 14 are new. Anchor Brackets are at Barriers 5 14, as shown in Plan View.
- **1d.** Typical Bracket and Top Plate positions shown in Plan View and Detail B. Top Plates at each joint from 5-6 to 13-14.







Roadside Safety and Physical Security Division -Proving Ground

Project 690900-IND-2

Drawn By GES

Indiana Barriers

2015-04-14

....

Scale 1:5

Sheet 2 of 6

Bracket Details




Plate Washer


Indiana Barriers Texas A&M
Transportation
Institute Project 690900-IND-2


Roadside Safety and Physical Security Division -Proving Ground


2015-04-14 Connector Straps

Drawn By GES

3a. These parts were supplied by the client. Material specifications were not provided.







Indiana Barriers Texas A&MTransportationInstitute Project 690900-IND-2

Roadside Safety and Physical Security Division -Proving Ground


Impact Path

Sheet 6 of 6

Scale 1:20


Drawn By GES

2015-04-14




| General Information | Impact Conditions | Post-Impact Trajectory |
|---|------------------------------------|---------------------------------------|
| Test Agency Texas A&M Transportation Institute (TTI) | Speed62.7 mi/h | Stopping Distance 240 ft dwnstrm |
| Test Standard Test No MASH Test 3-11 | Angle25.3 degrees | 54 ft twd traffic |
| TTI Test No 690900-IND2 | Location/Orientation4.7 upstrm 8-9 | Vehicle Stability |
| Date 2015-04-16 | Impact Severity121.1 kip*ft | Maximum Yaw Angle54 degrees |
| Test Article | (+5%) | Maximum Pitch Angle 18 degrees |
| Type Temporary Concrete Barrier | Exit Conditions | Maximum Roll Angle 18 degrees |
| Name Indiana Anchored Temporary Barrier with | Speed53.8 mi/h | Vehicle SnaggingNo |
| Wedge Anchor Studs and Top Connectors | Angle4.8 degrees | Vehicle PocketingNo |
| Installation Length 201.6 ft | Occupant Risk Values | Test Article Deflections |
| Material or Key Elements 9 ft-11 inch F-shape concrete barriers | Longitudinal OIV15.1 ft/s | Dynamic |
| anchored with steel anchor brackets, wedge | Lateral OIV24.6 ft/s | Permanent |
| anchor studs, 4-bolt top plates in pockets | Longitudinal RDA5.1 G | Working Width |
| Soil Type and Condition Concrete pavement, dry | Lateral RDA11.2 G | Vehicle Damage |
| Test Vehicle | THIV31.9 km/h | VDS 11LFQ5 |
| Type/Designation 2270P | PHD11.7 G | CDC |
| Make and Model | ASI | Max. Exterior Deformation 12.0 inches |
| Curb | | |
| Test Inertial | Longitudinal 50-ms Average7.7 G | OCDIFS0000000 |
| | Lateral 50-ms Avg12.5 G | Max. Occupant Compartment |
| Dummy | Vertical 50-ms Avg4.1 G | DeformationNone |
| Gross Static 5044 lb | | |

 $Figure \ 5.9. \ Summary \ of \ Results \ for \ \textit{MASH} \ Test \ 3-11 \ on \ Indiana \ Anchored \ Temporary \ Barrier \ with \ Wedge \ Anchor \ Studs.$



- 1a. Nominal concrete apron thickness. Actual thickness may be up to 1" greater or less.
- **1b.** Install Wedge Anchors according to manufacturer's instructions with 4-1/2" embedment. Two at each Bracket. Tighten to 250ft/lbs (minimum according to manufacturer's specifications).
- **1c.** Barriers 1 4 and 15 20 were used in a previous test. Barriers 5 14 are new. Anchor Brackets are at Barriers 5 14, as shown in Plan View.
- 1d. Typical Bracket and Top Plate positions shown in Plan View and Detail B.






2a. This part was supplied by the client. Material specifications were not provided.

Sheet 2 of 6 Scale 1:5 Project 690900-IND-3 Drawn By GES

Indiana Barriers

Bracket Details



Wedge Anchor Socket, Ø1" x 5" (Internal threads not shown)



Roadside Safety and Physical Security Division -Proving Ground


2015-05-14 Connector Hardware


Sheet 3 of 6


Scale 1:5

Drawn By GES

3a. These parts were supplied by the client. Material specifications were not provided.







Indiana Barriers Texas A&M
Transportation
Institute Project 690900-IND-3

Roadside Safety and Physical Security Division - Proving Ground

Impact Path

Sheet 6 of 6

Scale 1:20

Drawn By GES

2015-05-14

Gross Static..... 5021 lb




Figure 5.10. Summary of Results for MASH Test 3-11 on the Indiana Anchored Temporary Barrier with Wedge Anchor Studs and Modified Top Connection.

Vertical -4.5 G



Texas A&M Transportation Institute 3135 TAMU College Station, TX 77843-3135

979-845-6375 Fax: 979-845-6107 http://tti.tamu.edu/crashtesting

November 4, 2015

Nick Artimovich
Federal Highway Administration
Office of Safety Design
U. S. Department of Transportation – HSSD
1200 New Jersey Avenue, SE
Washington, DC 20590

RE: Test No. 690900-IND3 Financial Information

Dear Mr. Artimovich:

In an e-mail dated October 21, 2015, to Mr. Rick Drumm of Indiana Department of Transportation, you requested additional information regarding the financial interest that the crash test laboratory had/has in the product for which Indiana DOT was requesting a letter of eligibility.

The e-mail stated that financial interests include but are not limited to —

- Compensation, including wages, salaries, commissions, professional fees, or fees for business referrals;
- (ii) Consulting relationships
- (iii) Research funding or other forms of research support;
- (iv) Patents, copyrights, and other intellectual property interests;
- (iv) Licenses or contractual relationships; or
- (v) Business ownership and investment interests.

In regard to the Indiana DOT Temporary Anchored Concrete Barrier, TTI Proving Ground had/has no financial interests. Indiana DOT contracted for the service of crash testing this barrier according to specifications for American Association of State Highway and Transportation Officials (AASHTO) *Manual for Assessing Safety Hardware (MASH)* Test 3-11, for which TTI Proving Ground was compensated for the cost to perform the test.

No consulting relationships, research funding or other forms of research support, patents, copyrights, other intellectual property interests, licenses, contractual relationships, business ownership or investment interests are retained for the TTI Proving Ground.

If further information is needed, please feel free to contact TTI Proving Ground by phone at 979-845-6388 or e-mail <u>d-zimmer@tti.tamu.edu</u>.

Sincerely,

Richard A. Zimmer

Proving Ground Director

A better job done safer and sooner.

TTI Proving Ground 3100 SH 47, Bldg. 7091 Bryan, TX 77807



Texas A&M Transportation Institute 3135 TAMU College Station, TX 77843-3135

979-845-6375 Fax: 979-845-6107 http://tti.tamu.edu

November 30, 2015

Indiana Department of Transportation 100 North Senate Avenue Indiana Government Center North Room N644 Indianapolis, IN 46204

Attention: Mr. John Wright

Subject: MASH Test 3-11 of the Indiana Anchored Temporary Concrete Barrier

John,

This letter is in response to your e-mail dated October 22, 2015. The purpose of this letter is to address/respond to two of the four comments from this e-mail. The remaining two comments will be addressed separately by other(s) in a separate letter. TTI performed two successful crash tests with respect to MASH Test Level 3 on the Indiana Anchored Temporary Concrete Barrier with wedge anchor studs and top barrier plates (see TTI test reports 690900-IND2 and dated 2015-04-16, and 690900-IND3 and dated 2015-05-19).

ITEM 2: A statement is needed from TTI that MASH Test 3-10 is not a critical test for a concrete safety-shape barrier.

TTI RESPONSE: The tests reported herein correspond to Test 3-11 of MASH (5000-lb pickup, 62 mi/h, 25 degrees). This test was deemed sufficient to evaluate the impact performance of the temporary concrete barrier with anchor plates and bent plate anchor brackets. Due to higher impact energy, the test with the 5000-lb pickup truck will result in greater load on the anchoring pins, lateral barrier deflection, and vehicle instability. The barrier is expected to behave nearly rigidly when impacted by the lighter 2425-lb passenger car. In the past, a rigid New Jersey barrier, which is generally considered to be more critical in terms of vehicle stability than the F-shape barrier, has been successfully tested under MASH Test 3-10 conditions (Midwest Roadside Safety Facility test 2214NJ-1). Thus, only MASH test 3-11 was conducted on the Indiana Anchored Temporary Concrete Barrier.

ITEM 3: A response from TTI to John Wright's letter of 7/27/2015 regarding recess for the top plate and ferrule loops versus field-drilled holes.

TTI RESPONSE: As a result of the crash tests conducted on April 16, 2015 and May 19, 2015, there were some minor differences in the top plate configuration. Test 2 utilized a 4-bolt top plate system with a recessed section for the plate. The bolts were secured to ferrule loops that were formed into the concrete. Test 3 utilized a 2-bolt top plate system with no recessed area for the plate. The bolts were secured into field-drilled holes with expansion anchors.

Roadside Safety and Physical Security Systems The anchoring concepts used for each test are described as follows, along with my summary for use of each anchoring system in the field.

- Test 3 confirmed that the 2-bolt top plate system resulted in a successful crash test; therefore, we believe that either the 4-bolt or the 2-bolt system is satisfactory. No comment needed.
- 2. Test 2 had a recessed area for the top plate; Test 3 did not. We believe the recessed concrete area is a nonissue and could be used in either case.
- 3. Test 2 used ferrule loops formed into the concrete; Test 3 used field-drilled holes and expansion anchors to secure the bolts in the top plate. I believe that the top plate anchoring system can use either method. The top plate bolt is not torqued to any specific value, only sugged. Since both systems worked satisfactorily, I believe that the anchoring systems are interchangeable.

If you have any questions, please contact me at 979-862-2297 or via e-mail at w-williams@tti.tamu.edu.

a (Ve. 00.

Thanks.

William Williams, P.E.

Associate Research Engineer

Texas A&M Transportation Institute

3135 TAMU

College Station, TX 77843-3135

(wk.) 979-862-2297

E-mail: w-williams@tti.tamu.edu



Texas A&M Transportation Institute 3135 TAMU College Station, TX 77843-3135

979-845-6375 Fax: 979-845-6107 http://tti.tamu.edu/crashtesting

November 2, 2015

Nick Artimovich
Federal Highway Administration
Office of Safety Design
U. S. Department of Transportation – HSSD
1200 New Jersey Avenue, SE
Washington, DC 20590

RE: Test No. 690900-IND3 use of a 2008 pickup truck

Dear Mr. Artimovich:

On May 15, 2015, the Texas A&M Transportation Institute (TTI) performed a TL-3 crash test on the Indiana Anchored Temporary Concrete Barrier with wedge anchor studs and modified top connection (690900-IND3) for the Indiana Department of Transportation. The test passed "preferred" criteria for occupant impact velocity and ridedown acceleration and other requirements specified in *MASH* (see Attachment 1) and a report was generated. Federal Highway Administration (FHWA) has subsequently pointed out that the vehicle used in this test did not meet MASH recommendations in regard to age (it was one model year too old). This document is a request for an exception from FHWA, and explains differences and similarities between the 2008 Dodge 1500 quad-cab used in the test and the 2009 model of the same vehicle.

The Dodge 1500 quad-cab, short-bed configuration is a staple for *MASH* testing. This is the truck selected for all 2270P pickup truck testing for the past several years at the TTI Proving Ground due to its availability, cost, and consistency in specifications between trucks. A random sample of 2270P vehicle property data sheets pulled from recent crash test reports is provided in Attachment 2. These data sheets were used to compare key vehicle specifications for model year 2008 and 2009 pickup trucks. As shown in Table 1, key specifications such as CG location (longitudinal and vertical), overall length, and wheelbase remain basically unchanged between the two model years.

Figure 1 shows pictures comparing and contrasting the 2008 and 2009 year models. Changes between the model years are mostly cosmetic with one mechanical difference. The front clip including the bumper and fenders are different between the trucks as shown in Figures 1 and 2.

There was also a change in the rear suspension in the 2009 model year. The leaf spring suspension that is common on most half-ton trucks on the road was changed to a coil spring rear suspension with a panhard type bar that limits lateral movement of the rear axle. This newer style suspension has been marketed as being able to improve the stability of a vehicle while turning compared to a leaf spring suspension. When discussing the new rear suspension in 2009,

Edmunds, a popular automotive publication, stated "the real payoff here is superior unladen ride and improved cornering stability." Figures 3 and 4 show the rear suspensions for the two different model year trucks.

In conclusion, while differences exist between the two vehicle model years, we believe that these differences would not have produced different test results. We respectfully ask that FHWA grant an exception for the use of a 2008 model year pickup truck in the subject test. TTI purchased this vehicle to perform a crash test in the prior year when the project contract was originally signed. Delays in the project led to the test date being pushed into the subsequent calendar year and the error was not caught. After a laboratory investigation, it was determined that an existing test preparation protocol document was not sufficient for preventing this error and this document has since been amended as a result. TTI ensures FHWA that the internal process that permitted this error to occur has been corrected and new procedures now in place will prevent this from occurring again in the future.

If additional information is needed regarding this issue, please do not hesitate to call me at 979-845-6388 or e-mail me at <u>d-zimmer@tti.tamu.edu</u>.

Sincerely,

Richard A. Zimmer

Proving Ground Director

TTI Proving Ground

cc: D. Lance Bullard, Jr., TTI

John Wright, Indiana DOT

Roger Bligh, TTI

William Williams, TTI

T:\\1-ProjectFiles\690900-Compliance\IND-IndianaDOT-Williams

¹ http://www.edmunds.com/car-reviews/track-tests/2009-dodge-ram-1500-suspension-walkaround.html

Table 1. Vehicle Properties Comparison.

| Property | MASH 2270P (Pickup Truck) | Model Year 2008 (Average of 3 Test Vehicles) | 690900-IND3 (Model Year 2008) | Model Year 2009 (Average of 4 Test Vehicles) |
|---|--|--|---|--|
| MASS, Ib Test Inertial Max. Ballast | 5000 ± 110 440 | 5016 | 5021 | 5034 |
| DIMENSIONS, inches Wheelbase Front Overhang Overall Length Overall Width Hood Height Track Width ^a | 148 ± 12 39 ± 3 237 ± 13 78 ± 2 43 ± 4 67 ± 1.5 | 140.5 36.0 223.75 78.25 45.8 68.5 | 140.5 36.0 223.75 78.25 44.5 68.25 | 140.5 40.0 227.5 78.5 44.5 68.5 |
| CENTER OF MASS LOCATION,b inches Aft of Front Axle Above Ground | 63 ± 4 28.0 | 61.30 28.29 | 62.06 28.5 | 61.48 28.25 |
| LOCATION OF ENGINE | Front | Front | Front | Front |
| LOCATION OF DRIVE AXLE | Rear | Rear | Rear | Rear |

a Average of front and rear axles.
b For "test inertial" mass.
c 2270P vehicle must meet minimum c. g. height requirement



Figure 1. Model year 2009 on Left, 2008 on Right. Differences in grill, bumper and headlights.



Figure 2. Differences between fender lines exist between the 2008 and 2009 year models.



Figure 3. The 2008 model year employs a leaf spring rear suspension.



Figure 4. The 2009 model year employs a coil spring and panhard bar configuration.

ATTACHMENT 1: Results of MASH Test 3-11 on Indiana Temporary Anchored Barrier





Figure 5.10. Summary of Results for MASH Test 3-11 on the Indiana Anchored Temporary Barrier with Wedge Anchor Studs and Modified Top Connection.

Table 6.1. Performance Evaluation Summary for MASH Test 3-11 on the Indiana Anchored Temporary Barrier with Wedge Anchor Studs and Modified Top Connection.

| Tes | t Agency: Texas A&M Transportation Institute | Test No.: 690900-IND3 | est Date: 2015-05-19 |
|-----|--|--|----------------------|
| | MASH Test 3-11 Evaluation Criteria | Test Results | Assessment |
| Stn | actural Adequacy | | |
| A. | Test article should contain and redirect the vehicle or bring the vehicle to a controlled stop; the vehicle should not penetrate, underride, or override the installation although controlled lateral deflection of the test article is acceptable | The Indiana Anchored Temporary Barrier with Wedge Anchor Studs and Modified Top Connection contained and redirected the 2270P vehicle. The vehicle did not penetrate, underride, or override the installation. Maximum dynamic deflection during the test was 13.3 inches. | Pass |
| | eupant Risk | | |
| D. | Detached elements, fragments, or other debris from the test article should not penetrate or show potential for penetrating the occupant compartment, or present an undue hazard to other traffic, pedestrians, or personnel in a work zone. | No detached elements, fragments, or other debris was present to penetrate or to show potential for penetrating, the occupant compartment, or to present hazard to others in the area. | Pass |
| | Deformations of, or intrusions into, the occupant compartment should not exceed limits set forth in Section 5.3 and Appendix E of MASH. | Maximum deformation of the occupant compartment was 1.25 inches in the left lower kick panel area. | Pass |
| F. | The vehicle should remain upright during and after collision. The maximum roll and pitch angles are not to exceed 75 degrees. | Maximum roll and pitch angles were 26 degrees and 25 degrees, respectively. | Pass |
| Н. | Longitudinal and lateral occupant impact velocities should fall below the preferred value of 30 ft/s, or at least below the maximum allowable value of 40 ft/s. | Longitudinal OIV was 16.7 ft/s, and lateral OIV was 24.3 ft/s. | Pass |
| 1. | Longitudinal and lateral occupant ridedown accelerations should fall below the preferred value of 15.0 Gs, or at least below the maximum allowable value of 20.49 Gs. | Maximum longitudinal RDA was 8.9 Gs, and maximum lateral RDA was 10.8 Gs. | Pass |



APPENDIX D. CRASH TEST NO.

VEHICLE PROPERTIES AND INFORMATION D1.

Table D.1. Vehicle Properties for Test No.

| Date: | | | | . Test No | o.: . | | | VIN No | o.: <u>1D7H/</u> | <u> 1824855</u> | <u> 609</u> | <u> 14 </u> |
|------------------|---------------------------|-----------------------|--------------|--------------------|--------|-----------------------------|---------------|---------------------|------------------|-------------------|-------------|--|
| Year: | 2008 | | | Mak | e: _ | Dodge | | Mode | el: <u>Ram 1</u> | 500 | | |
| Tire Si | ze: _ | 265/7 | '0R17 | | | | Tir | e Inflation P | ressure: _ | 35 psi | | |
| Tread | Туре: | Highv | vay | | | | | Od | lometer: _ | 136075 | | |
| Note a | ny dama | age to | the vel | hicle prior | to te | est: No | ne | | | | | |
| • Den | otes acc | eleron | neter k | ocation. | | | | W | | | | |
| NOTE | S: | - | | | | | | | | | | |
| Engine Engine | Type: | V-1 5.7 | 8 7 liter | | | A M | EFFI ACK | | - | | | N WHERE TRACK |
| Transn | nission 1 Auto FWD | or | RWD | _ Manual 4W | | 1 | | +Q+ | | TEST INERTI | AL C. M | |
| Option Nor | al Equip | | INVID | 470 | | | P - R - | | | 0 | | |
| Type: Mass | : | NA | | | _ | 1 1-1 | - F | U H H | -G -G | | _D- | J _K L, |
| Geom | Position etry: | : <u>NA</u> inches | - | | | | | PROHT | C | V) | M AR | |
| Α | 78.25 | | F_ | 36.00 | | κ | 21.00 | Р | 2.88 | | U | 28.50 |
| В | 75.00 | | G | 28.50 | | L | 29.50 | Q | 30.50 | | v _ | 30.50 |
| c _ | 223.75 | | Η _ | 61.31 | | M | 68.50 | R | 16.00 | | w ackslash | 61.30 |
| D | 47.25 | | ١ _ | 16.00 | | Ν | 68.00 | s | 15.50 | | x _ | 77.00 |
| E | 140.50 | | J_ | 28.00 | | 0 _ | 46.00 | T | 77.50 | | _ | |
| | neel Cente leight Fron | | | 14.75 | Clea | Wheel Wel trance (Front) | | 6.00 | | Frame - Front | | 18.75 |
| | neel Cente leight Rea | | | 14.75 | Clea | Wheel Wel arance (Rear | | 11.00 | Bottom | Frame I - Rear | | 26.00 |
| RANGE | ELIMIT: A=7 | 8 ±2 inche | s; C=237 : | 13 inches; E=1 | 18 ±12 | inches; F=39 ±3 | inches; G = : | > 28 inches; H = 63 | ±4 inches; O=43 | ±4 inches; M+ | N/2=67 | ±1.5 inches |
| GVW | R Rating | gs: | | Mass: | lb | <u>C</u> | <u>urb</u> | <u>Te</u> | st Inertial | | <u>Gro</u> | ss Static |
| Front | | 370 | 0_ | M _{front} | | | 2880 | | 2829 | | | |
| Back | | 390 | 0 | M _{rear} | | | 1978 | | 2194 | | | |
| Total | | 670 | 0 | M_{Tota} | 1 | | 4858 | abla Danes Garage | 5023 | | | |
| Mass (| Distribu | tion: | | | | | (Aliow | vable Range for TIM | and G5M ≈ 5000 | vio ±110 (b) | | |
| lb | | | LF: | 1451 | | RF: | 1378 | LR: | 1047 | RR: | 1 | 1147 |



5.4.8.1P Vehicle Parameter Worksheet for 2270P Pickup

Doc. No. Revision Date: QPF 5.4.8.1P VPWS 2012-09-14 Revision: Page:

Quality Policy Form

Revised by: W. L. Menges Approved by: R. A. Zimmer

1 of 1

| Vehicle Invento | |
|--|---|
| Date: Test No.: | VIN No .: 1 D7HA18NK45813252 |
| Year: Zook Make: | DoDGE Model: Ram 1500 |
| Tire Size: 765/78 817 | Tire Inflation Pressure: SS PSI |
| Tread Type: HICHWA-/ | Odometer: 199140 |
| Note any damage to the vehicle prior to te | st: |
| Denotes accelerometer location. | - W |
| NOTES: | A M. N. T. |
| Engine CID: 4.7 L | TALKE TALKE |
| Transmission Type: Auto or ManualFWD RWD 4WD Optional Equipment: | TEST BREXTIAL C.M |
| Dummy Data: Type: Mass: Seat Position: | F H G V S |
| Wheel Center Height Rear 1 4.75 Clear RANGELIMIT: A-78 ±2 inches; C-237 ±13 inches; E-148 ±12 inches | REGIT 1323. |
| GVWR Ratings: Mass: Ib Front 3700 M _{front} | Curb Test Inertial Gross Static 2852 2864 — |
| Back 3900 Mrear | 7605 2203 - |
| Total 6708 M _{Total} Mass Distribution: Ib LF: 1393 | HS57 S007 T Allowable Range for TIM and GSM = 5000 lb ±110 lb) RF: H LR: H D RR: 1093 |

APPENDIX F. CRASH TEST NO.

F.1 VEHICLE PROPERTIES AND INFORMATION

Table F.1. Vehicle Properties for Test No. Date: Test No.: VIN No.: 1D7HA18N785614698 2008 Year: Make: Dodge Model: Ram 1500 Tire Size: 265/70R17 Tire Inflation Pressure: 35 psi Tread Type: Highway Odometer: 159444 Note any damage to the vehicle prior to test: None Denotes accelerometer location. NOTES: NA WHEEL TRACK Engine Type: V-8 4.7 liter Engine CID: **Transmission Type:** TEST DIERTIAL C M _x Auto Manual FWD x RWD **Optional Equipment:** None ŀκ **Dummy Data:** Type: No Dummy Lg Mass: **Seat Position:** NA Geometry: inches U 28.50 20.25 Р 2.88 78.25 F 36.00 K 30.50 V 30.50 В 75.00 G 28.38 L 29.00 Q C 223.75 Н 60.76 М 68.50 R 16.00 W 60.70 D 47.25 15.50 Ν 68.00 S 15.00 Х 77.00 T 77.50 Ε 0 45.50 140.50 25.26 Wheel Well **Bottom Frame** Wheel Center 6.00 18.50 14.75 **Height Front** Clearance (Front) Height - Front **Bottom Frame** Wheel Well Wheel Center 11.00 25.00 14.75 Height Rear Clearance (Rear) Height - Rear RANGE LIMIT: A=78 ±2 inches; C=237 ±13 inches; E=148 ±12 inches; F=39 ±3 inches; G = > 28 inches; H = 63 ±4 inches, O=43 ±4 inches; M+N/2=67 ±1.5 inches **GVWR Ratings:** Mass: Ib Curb **Test Inertial Gross Static** 2849 3700 2885 2849 **Front** Mfront 2171 Back 3900 Mrear 2076 2171 5020 5020 Total 6700 4961 MTotal (Allowable Range for TIM and GSM = 5000 lb ±110 lb) Mass Distribution:

lb

1093

RR:

1078

LR:

1407

RF:

1442

LF:

APPENDIX C. CRASH TEST NO. 690900-IND3

C.1 VEHICLE PROPERTIES AND INFORMATION

Table C.1. Vehicle Properties for Test No. 690900-IND3.

| Date: 201 | 5-05-15 | Test No.: | 690900 | -IND3 | _ VIN No | .: <u>1D7HA18N9</u> | 9855563 | 7 |
|-----------------------------|---|-------------------|--------------------|-------------|-----------------------|----------------------------------|-----------------|--------------------------|
| Year: 200 | 3 | Make: | Dodge | | _ Mode | l: <u>Ram 1500</u> | | |
| Tire Size: | 265/70R17 | 7 | | Tire | Inflation Pr | essure: 35 ps | i | |
| Tread Type: | Highway | | | | Od | ometer: <u>1993</u> 4 | 48 | |
| Note any dan | nage to the v | ehicle prior to t | est: <u>N</u> | lone | | | | |
| Denotes ac | celerometer | location. | | | - W | | | |
| NOTES: No | one | | 1 1 | | | | | |
| | | | | . [| | | | |
| Engine Type: Engine CID: | V-8 4.7 liter | | | WHEEL | | | = } | N T |
| Transmission | • • | Manual | ,- | \\ | | -TEST | INERTIAL C M | |
| _x Auto FWD | or _x RWD | Manual 4WD | | R - 1 | | | | |
| Optional Equi | pment: | | 1 | P | | | <u> </u> | В |
| Dummy Data: | | |] 1- | | | | $\bigcirc)_{f}$ | D_{K} |
| Type: | No Dun | nmy | . | | U | L _v L _s | | _ |
| | Mass: NA F→ H→ H G D→ | | | | | | | - |
| Goomotau | inches | | | | M PRONT | | M REAR | |
| Geometry: A 78.25 | inches F | 36.00 | К | 21.50 | P | —- c ——— 2.88 | U | - ►l 28.50 |
| B 75.00 | | 28.50 | . '` - | 30.00 | - | 30.50 | v – | 30.50 |
| C 223.75 | | 62.06 | . – – М | 68.50 | - • . R | 18.00 | w | 62.00 |
| D 47.25 | | 15.25 | . N | 68.00 | s · | 16.00 | x _ | 77.00 |
| E 140.50 |) J | 26.75 | 0 | 44.50 | - T | 77.50 | _ | |
| Wheel Cen Height Fro | | 14.75 Cle | Wheel Warance (Fro | | - 6.00 | Bottom Frame Height - Front | | 18.50 |
| Wheel Cen Height Re | | | Wheel Warance (Re | /ell | 11.00 | Bottom Frame Height - Rear | , | 25.00 |
| • | | | | | | t4 inches; O=43 ±4 inches | | |
| GVWR Ratir | ıgs: | Mass: Ib | | <u>Curb</u> | Tes | st Inertial | Gros | s Static |
| Front | 3700 | M_{front} | | 2888 | | 2803 | | 2803 |
| Back | 3900 | M_{rear} | | 2068 | | 2218 | | 2218 |
| Total | 6700 | M_{Total} | - | 4956 | la Rosso for Tibe | 5021 and GSM = 5000 lb ±110 l | , | 5021 |
| Mass Distrib | | | | | ra ivenila ini iliM (| 10112 di UUU¢ ← MCO MB | , | |
| lb | LF | 1428 | RF: | 1375 | LR: | | RR:1 | 121 |



Doc. No. Revision 5.4.8.1P Vehicle Date: QPF 5.4.8.1P **VPWS** 2012-09-14 2270P Pickup Revision: Page:

Parameter Worksheet for Revised by: W. L. Menges Approved by: R. A. Zimmer **Quality Policy Form** 7 1 of 1

| Vehicle Inventory N | Number: 1054 | |
|--|---|-----|
| Date: Test No.: | VIN No.: 103/18/15P3957705 | 31 |
| Year. <u>7069</u> Make: <u>Dot</u> | Model: San 1500 | |
| Tire Size: 265/70 K 17 | Tire Inflation Pressure: 35 PSF | |
| Tread Type: 1156Hussy | Odometer: 164178 | |
| Note any damage to the vehicle prior to test: | | |
| Denotes accelerometer location. | - X | |
| NOTES: | M | T |
| Engine CID: U.1 L | TRACK WHITZ | |
| Transmission Type: Auto or Manual FWD RWD 4WD | TEST BREATIAL C M. | |
| Optional Equipment: | | В |
| Dummy Data: Type: Mass: Seat Position: DA. IVER SSDE | F H E W S | t v |
| Geometry: inches | FRONT PEAN | |
| B 73.5 G 28.25 L C 227.5 H 63.08840 M D 47 I 0.5 N E 140.5 J 25.25 O | S 12.75 X 77 44.5 T 77 | _ |
| Wheel Center Height Front Wheel Center Height Rear Wheel Clearance (Wheel Clearance (Clearance (RANGE LIMIT: A=78 ±2 Inches; G=237 ±13 Inches; E=148 ±12 Inches; F | Front) 4.75 4 Height - Front 17 HWell Rear) 7.75 Height - Front 25.5 | _ |
| GVWR Ratings: Mass: Ib | Curb Test Inertial Gross Static | |
| Front 1791 3700 M _{front} | 7867 7718 7860 | - |
| Back 1776 3900 M _{rear} 2 | 2126 2042 2347 | - |
| Mass Distribution: Ib LF: 1393 RF | (Allowable Range for TIM and GSM = 5000 lb ±110 lb) | |

Vehicle Properties for Test No.

APPENIDX B. CRASH TEST NO.

(MASH TEST 3-11)

B1 VEHICLE PROPERTIES AND INFORMATION

Table B.1.

Date: Test No.: VIN No.: 1D3HB18T99S704322 2009 Year: Make: Dodge Model: Ram 1500 Tire Inflation Pressure: 35 psi Tire Size: 265/70R17 Tread Type: Highway **Odometer: 171412** Note any damage to the vehicle prior to test: • Denotes accelerometer location. NOTES: NA Engine Type: WHEEL V-8 Engine CID: 4.7 Liter Transmission Type: TEST INERTIAL C. M _x_ Auto Manual FWD **Optional Equipment:** NA k **Dummy Data:** Type: None Mass: NA Seat Position: NA Geometry: inches Α F 78.50 40.00 K 20.25 Р 3.00 U 28.50 В G L Q 73.50 28.25 29.50 ٧ 29.50 30.50 C 227.50 Н 60.04 R M 68.50 18.00 W 60.00 D 47.00 10.50 Ν S 12.75 68.00 77.00

RANGE LIMIT: A=78 ±2 inches; C=237 ±13 inches; E=148 ±12 inches, F=39 ±3 inches, G = > 28 inches, H = 63 ±4 inches; O=43 ±4 inches; M+N/2=67 ±1.5 inches

44.50

T

6.00

9.25

77.00

Bottom Frame

Height - Front

Bottom Frame

Height - Rear

0

Clearance (Front)

Clearance (Rear)

Wheel Well

Wheel Well

25.25

14.75

14.75

| GVWR R | atings: | Mass: Ib | Curb | Test Inertial | Gross Static |
|-----------|-----------|--------------------|--------------|--|--------------|
| Front _ | 3700 | M _{front} | 2963 | 2872 | 2872 |
| Back _ | 3900 | M _{rear} | 1984 | 2143 | 2143 |
| Total | 6700 | M _{Total} | 4947 | 5015 | 5015 |
| Mace Diet | ribution: | • | (Allowable R | tange for TIM and GSM = 5000 lb ±110 lb) | |

Mass Distribution:

140.50

Wheel Center

Height Front

Height Rear

Wheel Center

E

lb LF: <u>1430</u> RF: <u>1442</u> LR: <u>1099</u> RR: <u>1044</u>

17.00

25.50

APPENDIX D. CRASH TEST NO.

(MASH TEST 5-11)

D.1 VEHICLE PROPERTIES AND INFORMATION

Table D.1. Vehicle Properties for Test No. Date: Test No.: VIN No.: 1D3HB18739S779243 2009 Make: Dodge Year: Model: Ram 1500 Tire Size: 265/70R17 Tire Inflation Pressure: 35 psi Tread Type: Highway Odometer: 163126 Note any damage to the vehicle prior to test: None Denotes accelerometer location. NOTES: NA **Engine Type:** V-8 **Engine CID:** 4.7 liter Transmission Type: TEST INERTIAL C. M x Auto Manual FWD RWD 4WD Optional Equipment: None Fκ **Dummy Data:** 50th percentile male Type: Mass: 165 lb ٠G Seat Position: Right front M FROIT Geometry: inches Α 78.50 F 40.00 K 20.25 Р 3.00 U 28.50 В 73.50 G 28.12 L Q 29.50 30.50 ٧ 29.50 C 227.50 Н 61.25 М R 68.50 18.00 W 61.20 D 47.00 10.50 S Ν 68.00 12.25 77.00 Х Ε 140.50 25.25 0 44.50 T 77.00 Wheel Center Wheel Well **Bottom Frame** 14.75 **Height Front** 6.00 Clearance (Front) 17.00 Height - Front Wheel Center Wheel Well **Bottom Frame** 14.75 9.25 Height Rear Clearance (Rear) 25.50 Height - Rear **GVWR Ratings:** Mass: Ib Curb **Test Inertial Gross Static** M_{front} Front 3700 2889 2844 2929 Back 3900 Mrear 2146 2198 2278 Total 6700 M_{Total} 5035 5042 5207 **Mass Distribution:** lb LF: 1452 RF: 1392 LR: 1110

1088

RR:

APPENIDX C. CRASH TEST NO.

(MASH TEST 3-36)

C1 VEHICLE PROPERTIES AND INFORMATION

Table C.1. Vehicle Properties for Test No.

| Date: _ | | | Test No.: | _ | | _ VIN No.: | 1D3HB | 18P49S75 | 9912 |
|--|-----------------|----------|----------------------|------------------------|---------------|--------------------------|----------------------|--------------|---------------------|
| Year: 2 | 009 | | Make: | Dodge | | _ Model: | Ram 15 | 500 | |
| Tire Size: | 265/70 |)R17 | | | Tire | Inflation Pre | ssure: _3 | 35 psi | |
| Tread Type | e: <u>Highw</u> | ay | | | | Odo | meter: _1 | 150600 | <u> </u> |
| Note any d | lamage to t | he vet | nicle prior to t | est: <u>1</u> | None | | | | |
| Denotes accelerometer location. | | | | | | | | | |
| NOTES: | NA | | | | | 7/ | | | |
| Engine Type | | liter | | | A WHEEL TRACK | | | | N WHIERA |
| Transmission Type: x Auto or Manual FWD x RWD 4WD R | | | | | | | | | |
| Optional E | quipment: | | | | P | 7.00 | | ° | |
| Dummy Da Type: Mass: Seat Posi | Nor NA | ne | | J - | 1-F- | U | G V | -s -1 | TK L |
| Geometry | | , | | | , | M FRONT | | M REAR | |
| - | 3.50 | F | 40.00 | К | 20.25 | Р | -с- 3.00 | U | — → 28.50 |
| | 5.50 | G | 28.38 | L | 29.50 | | 30.50 | _ v | 29.50 |
| C 227 | | н - | 61.54 | M | 68.50 | <u>-</u> | 18.00 | v | |
| D 47 | 7.00 | 1 [| 10.50 | N | 68.00 | - s - | 12.75 | x | 77.00 |
| E 140 | | J _ | 25.25 | 0 | 44.50 | T T | 77.00 | | |
| Wheel (Height | | | 14.75 Cle | Wheel V arance (Fro | | 6.00 | Bottom F Height - | | 17.00 |
| Wheel (Height | Center | | | Wheel V arance (Re | Vell | 9.25 | Bottom F Height | Frame | 25.50 |
| • | | | 13 inches; E=148 ±1: | | | | | | |
| GVWR Ra | | | Mass: Ib | | <u>Curb</u> | | <u>Inertial</u> | | ross Static |
| Front | 3700 | <u> </u> | M_{front} | | 2865 | | 2832 | | 2832 |
| Back | 3900 | <u> </u> | M_{rear} | | 2168 | | 2207 | | 2207 |
| Total | 3700 | <u> </u> | M_{Total} | | 5033 | le Range for TIM and | 5039 | h 4110 (b) | 5039 |
| Mass Distr | ribution: | | | | | e van Ae i Oi i IIM (TU) | J G3m ≠ 5000 l | 5 X 1 10 (B) | |
| lb | | LF: | 1398 | RF: | 1434 | LR: | 1148 | RR: _ | 1059 |