

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/5/2022	<b>Time:</b> 10:02 AM
<b>Name of School Corporation:</b> AUXILIO SERVICES (MUNCIE)	<b>Corp ID:</b> 251807	
<b>Address of School Corporation:</b> 11260 Cornell Park Dr Suite 700		
<b>City:</b> Cincinnati	<b>Zip:</b> 45242	<b>County Number:</b> 18
<b>VIN:</b> 4DRBUC8P9JB524149	<b>License Number:</b> B483N	<b>Bus Number:</b> M4
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2019	<b>Make of Chassis:</b> IC Corporation
<b>Bus Type:</b> 4	<b>Mileage:</b> 47148	<b>Year:</b> 2018
<b>Inspection Status:</b> O	<b>Inspected By:</b> Jamie Hotchkiss	<b>PE:</b> 6458

**Comments:**

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>	<u>Comments</u>
26-1-4	Not securely mounted	Fire extinguisher bracket will not latch
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired	Seats 3 & 4 have holes in them.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-3	Stop arm does not fully extend to a right angle to the bus Stop arm extends out too far

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.