REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	8/3/2023	**Time:**	11:41 AM
Name of School Corporation:	NORTH WEST HENDRICKS SCHOOLS			**Corp ID:**	323295
Address of School Corporation:	PO Box 70				
City:	Lizton	**Zip:**	46149	**County Number:**	32
VIN:	1GB3GRBG6G1322464	**License Number:**	NWH162	**Bus Number:**	162
Make of Body:	Chevrolet **Year:** 2016	**Make of Chassis:**	Chevrolet	**Year:**	2016
Bus Type:	1	**Mileage:**	74260		
Inspection Status:	R	**Inspected By:**	Brandon Steffee	**PE:**	8247

Comments:

Violations - Rejected

Inspection Code	Description	Comments
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle	Missing d side / Faded pass side
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)	Loose items in header

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**