

# REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual **Date:** 8/3/2023 **Time:** 12:05 PM  
**Name of School Corporation:** NORTH WEST HENDRICKS SCHOOLS **Corp ID:** 323295  
**Address of School Corporation:** PO Box 70  
**City:** Lizton **Zip:** 46149 **County Number:** 32  
**VIN:** 1GB3GSBG4K1193012 **License Number:** K604534 **Bus Number:** 104  
**Make of Body:** Thomas Built Buses, Inc. **Year:** 2019 **Make of Chassis:** Chevrolet **Year:** 2019  
**Bus Type:** 2 **Mileage:** 37303  
**Inspection Status:** R **Inspected By:** Brandon Steffee **PE:** 8247

## Comments:

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>	<u>Comments</u>
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)	Loose crate of items on floor, passenger side, first seat.
90-1-5	See Notes: Any defect inspector deems a violation not listed	Loose container.
90-1-2	The trash container is greater than a fourteen (14) quart capacity	
34-1-1	Any headlight is inoperative	Passenger side headlight out.

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**